Allegan County Remonumentation LAND CORNER RECORDATION CERTIFICATE

in Section 3. Miscellaneous S T R Property in Sec. S T R 4. Lot No, Recorded Plat 5. Private Claims in a field survey on April 13, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.	FILED 1/28/1999 2:44:39 PM JOYCE A. WATTS RESISTER OF DEEDS ALLEGAN COUNTY, MICH pister of Deeds Stamp & File Number C D E F G H I J K L 5
1. Public Land Survey T4N R13W F-13 (St, 33) T R Salem Twp. T R S	1/28/1999 2:44:39 PM JOYCE A. WATTS REGISTER OF DEEDS ACLEGAN COUNTY, MICH pister of Deeds Stamp & File Number C D E F G H I J K L 5 4 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
TR R Salem Twp. TR R TR R R R R R R R R R R R R R R R R	JOYCE A. WATTS RESISTER OF DEERS ALLEGAN COUNTY, MICH pister of Deeds Stamp & File Number C D E F G H I J K L 5 4 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
2. Property Controlling S_ T_R S_ in Section S_ T_R S_ Section S_ S_ T_R S_	pister of Deeds Stamp & File Number C D E F G H I J K L 5 - 4 - 3 - 2 - 1 - 12 - 12 - 13 - 14 - 13 - 15 - 14 - 15 - 15
5. Private Claims (1. John C. Bueche	8 9 10 11 12 12 13 14 13 14 13 14 14 15 14 15 14 15 14 15 14 15 14 15 14 15 14 15 14 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15
5. Private Claims (1. John C. Bueche	
1, John C. Bueche, in a field survey on April 13, 19 98 do hereby state that under requirements of PA. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: F-13 GLO, 1831	3 — 17 — 16 — 15 — 14 — 13 — — 20 — 21 — 22 — 23 — 24 — — — — — — — — — — — — — — — — —
1, John C. Bueche, in a field survey on April 13, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: F-13 GLO, 1831	3 17 16 15 14 13
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: F-13 GLO, 1831	
A. Description of original monument and accessories and/or subsequent restoration: F-13 GLO, 1831	29 28 27 26 25
A. Description of original monument and accessories and/or subsequent restoration: F-13 GLO, 1831 LCRC 2-36, Sept., 1972 LCRC 4-387, Aug Lucius Lyon, DS Ratekin Found 3/4" iron Set 1/4 sec. post Found 3/4" iron N 79° W 125.00' Maple 16" bears N 68 E 35 7' N. of road C/L Quad. 16" Oak Maple 6" bears N 86 W 23 10" & 6" Tw. Oak S 42° W 67.20' N Old notes stake & stone S 45 W 67.0' NW Tw. 16" & 12 Oak 6" NW 88.4' TP N 80 W 87.29' N 86° E 132.66' N Oak 6" SW 67.0' S. side Tw. 16" O S 56° E 71.07' N 85. Description of corner evidence found and/or method applied in restoring or reestablishing corner: N. 8" Catalpa 2.5' F-13 Found 3/4" iron in gravel road; no field division North	
A. Description of original monument and accessories and/or subsequent restoration: F-13 GLO, 1831 LCRC 2-36, Sept., 1972 LCRC 4-387, Augustic Lucius Lyon, DS Ratekin Found 3/4" iron N 79° W 125.00' Maple 16" bears N 68 E 35 7' N. of road C/L Quad. 16" Oak Maple 6" bears N 86 W 23 10" & 6" Tw. Oak S 42° W 67.20' N Old notes stake & stone S 45 W 67.0' NW Tw. 16" & 12 Oak 6" NW 88.4' TP N 80 W 87.29' N 86° E 132.66' N Oak 6" SW 67.0' S. side Tw. 16" O S 56° E 71.07' N S. Side Tw. 16" O S 56° E 71.07' N S. Description of corner evidence found and/or method applied in restoring or reestablishing corner: N. 8" Catalpa 2.5' F-13 Found 3/4" iron in gravel road; no field division North	32 33 34 35 36
Lucius Lyon, DS Ratekin Found 3/4" iron Set 1/4 sec. post Found 3/4" iron N 79° W 125.00' Maple 16" bears N 68 E 35 7' N. of road C/L Quad. 16" Oak Maple 6" bears N 86 W 23 10" & 6" Tw. Oak S 42° W 67.20' N Old notes stake & stone S 45 W 67.0' NW Tw. 16" & 12 Oak 6" NW 88.4' TP N 80 W 87.29' N 86° E 132.66' N Oak 6" SW 67.0' S. side Tw. 16" O S 56° E 71.07' N8 Bescription of corner evidence found and/or method applied in restoring or reestablishing corner: N. 8" Catalpa 2.5"	
N. 8" Catalpa 2.5° F-13 Found 3/4" iron in gravel road; no field division North	N&T S. side &T 29245 Oak &T 29245 ak 4.5' high
<u>-</u>	high
And is accepted as a careful and faithful perpetuation of the position of the orig	APPROVED REMONUMENTATION CORNI P.A. 345 OF 1990 ALLEGAN COUNTY DATE APPROVED 1995 12, 199 COUNTY REP 12 1 10 10 10 10 10 10 10 10 10 10 10 10 1
. Description of monument for corner and accessories established to perpetuate locating the position of ti	
F-13 Replaced 3/4" iron with 3/4" x 24" Pin with Allegan Co. Cap in gravel road Nail & Allegan Co. Remon. Tag in N side 8" Sass S 40° E 71.14' Nail & Allegan Co. Remon. Tag in E side 8" Sass S 65° E 54.20' Nail & Allegan Co. Remon. Tag in W side 14" Elm S 35° W 34.02' Nail & Allegan Co. Remon. Tag in SW side 10" Sass N 50° W 48.82' Nail & Allegan Co. Remon. Tag in W side 6" Sass N 20° E 37.78' Allegan Co. Mon. F-1 (N 1/4 4, 3-13) West 60.50' C/L gravel road E-W is South 6'±	
signed by Cohn C Busche Date 5-8-9 Surveyor's Michigan License No. 13027	JOHN C * BUECHE LAND SURVEYOR No. 13027