## ALLEGAN COUNTY REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

25.7		_		*~			1
1	111	∍For	cor	ne	rs	in	( 3

	Allegan (County)	Located in:	Corner Code ##	Sp. 1993
1.	Public Land Survey	T _4N_ R .16W_ T R T R T R	—G-1-(NW-Sec-3) Laketown-Twp.	DEC 30 DEC 30 REGISTERO
2.	Property Controlling in Section	S T R S T R		
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
		Recorded Plat		A B C D E F G H I J X L N
doi in I cur Mai abo Coi	hereby certify that under re- ines 1 and 2 above were in rent manual of survey instr nagement or by a decree of ove were in conformance wi	in a field survey onNo quirements of P.A. 74, Michigan P.A. n conformance with regulations ar uctions of the United States Depar a Court of Lawand/or that the corn (th the rules of the Michigan Board or re-established, monumented, re-	of 1970, the corner points mention of rules therefore as required in t tment of the Interior, Bureau of La er points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of	led 6 10 17 16 15 14 13 19 19 19 19 19 19 19 19 19 19 19 19 19
NO	TE: Not more than 4 c	corners, all in the same town a	nd range, may be recorded	11 12 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3

A. Description of original monument and accessories and/or subsequent restoration:

	Government Notes	1831	Recorded in Liber 1 Page 31	Liber 1 Page 316 May 4, 1972		
	Post		These ties are to the closing	corner.		
	Beech 12" S16°W	20 links	The closing corner was 0.54	South of the Township	p line.	
	Beech 10" S60°E	33 links	1 1/4" diameter solid iron			
			CL: Ottogan Street	S	7.40*	
			12" Maple	S20°W	61.80*	
			28" Oak	S50°W	62.40*	
			Power Pole	S15°W	69.00*	
,	Description of corner oxide	unce found and/or math	ad applied 8" Marleina or reactable	hina aar \$7.5°E	76.20*	

G-

Found 1" square iron in monument box at closing corner using the above witnesses and accepted it as a careful and faithful reastablishment of the original corner. Set Allegan County Remonumentation Iron and Cap on South line Section 33, Town 5 North, Range 16 West, 0.54 North of the closing corner. This iron fits the monumented corners of Macatawa Bay Addition, (square iron in monument box).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-1 Set Allegan County Remonumentation Iron & Cap on Sout AZ - Michigan State Grid Direction	h line, Section 33, T5N, R16W.	DAVID R. DAVID R.
1" square iron in monument box	AZ.179°20'37* 0.54'	GREER
Set A.C. Remon tag & nail in SW Side 14" Oak	AZ. 222°51' 71.07'	LAND SURVEYOR
SE Cor Metal Bldg.	AZ. 35°43' 89.24'	No.
SW Cor Metal Bldg.	AZ. 300°48' 137.68'	16042
A.C. Remon tag & nail in SW Side 16" Maple	AZ. 152°58' 95.59'	MED LAND S
G-13, SE Cor, Sec. 33, T5N, R16W, remon		Manage .
ed by iron & Cap Council & Fren	AZ. 89°22' 124.66'	1//19/93

Surveyor's Michigan License No. 16542

Form approved by michigan state board of Land Surveyors, Jak. 28, 1971 Revised May 14, 1975 Revised Jan., 1983

WiDecriServillemen.dec

LIBER 004 PAGE 285