

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

ANTRIM  
 (County)

Located in: SEC 24 Corner Code #

- |                                    |   |            |   |           |            |
|------------------------------------|---|------------|---|-----------|------------|
| 1. Public Land Survey              | T | <u>30N</u> | R | <u>7W</u> | <u>M-8</u> |
|                                    | T | _____      | R | _____     | _____      |
|                                    | T | _____      | R | _____     | _____      |
|                                    | T | _____      | R | _____     | _____      |
| 2. Property Controlling in Section | S | _____      | T | _____     | _____      |
|                                    | S | _____      | T | _____     | _____      |
| 3. Miscellaneous Property in Sec.  | S | _____      | T | _____     | _____      |
|                                    | S | _____      | T | _____     | _____      |

**SECTION**

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

ANTRIM COUNTY  
 MICHIGAN  
 RECEIVED FOR RECORD  
 NOV 30 3 52 PM '94  
*Dennis R. Conway*  
 REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, NEIL L. WAY, in a field survey on OCT 5, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

M-8  
 GLO SET CORNER POST OCT 1855  
 BEECH 16 S20W 31  
 Beech 6 N64W 25

NO EVIDENCE FOUND

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-8  
 FOUND 1/2" IRON AND CAP WITH 1/2" X 3" X 18" BAR BESIDE IT.

Ratified by Peer Group  
 in accordance with P.A. 345  
 Chairman *Arthur L. Lennox*  
 Date: Oct. 6, 1994

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1-8  
 SET COUNTY MONUMENT  
 N57E 8.12' MPL 8"  
 S05E 19.47' ASH 12"  
 WEST 20.06' ASH 10"  
 NO2E 9.44' MPL 6"



Signed by NEIL L. WAY *Neil L. Way* Date NOV 21, 1994  
 Surveyor's Michigan License No. 28432

002 205