

FEB 1 1 1998

12-22-1997 10:11:27

المهاججة أنها

SECTION

Located In:

For corners in

ANTRIM

Liber 00002 Fase 0431

AMERIA COUNTY MI.

LAND CORNER RECORDATION CERTIFICATE Register of Deeds

Filing Requirement of Act 74. Mich. P.A. 1970. Filing Requirement of Act 74, Mich. P.A. 1970 Recorded CENTRAL LAKE

Corner Code #

(County)	Wanda R. Comway
1. Public Land Survey E 1/4 T_31N R_8W K-8 SEC 23 TR_	REGISTER OF DEEDS
T R	
7 R	
in Section S T R 3. Miscellaneous S T R	
Property in Sec. S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	дировечи так в
5. Private Claims	2 6 5 4 3 2 1
	3
	4
t, BICHARD J. KBAL , in a field survey on8-21-	
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as	
required in the current manual of survey instructions of the United States Depart Bureau of Land Management or by a decree of a Court of Law and /or the	
mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Land Surveyors or by a Decree of a Court of Law; established, re-established	e Michigan Board of 9
recovered, found as expressed below:	10 30 29 28 27 26 25
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	
on this certificate.	13
 A. Description of original monument and accessories and/or subsequent K-B, 1/4 CORNER COMMON TO SEC. 23 & 24, T31N-R8W 1857, SUBDIVISION OF TWP., RE-SURVEY BY E.D. ATWATER; SET 4" BEECH (27.72') 1969, SURVEY BY C.E. OSTLING, SHOWS CORNER AS 1/2" X 18" BAR & 2.30 IRON, WEST, 63.70' 1976, SURVEY BY N.B. DEYOUNG, SHOWS CORNER ON DRAWING, NO DESC B. Description of corner evidence found and/or method applied in restorments. Letter Common To Sec. 23 & 24, T31N-R8W FD. 1/2" IRON ROD 33' EAST OF CENTERLINE N-S. GR. ROAD PULED & REPLACED WITH ANTRIM COUNTY MONUMENT (BERNTSEN FD. 1/2" IRON ROD ON W. ROW ROAD N83°W, 63.56' (R. 63.70') FD. 1/2" IRON ROD ON E. ROW ROAD S83°E, 2.34' (R. 2.30') 	POST; 7" BEECH, N41°E, 9 LKS (5.94'); 5" BEECH, S52°W, 42 LKS O' INTO ROW. OF RD. NO ACCESSORIES GIVEN, OTHER THAN A ROW. RIPTION OR ACCESSORIES, OTHER THAN A ROW. IRON, WEST, oring or reestablishing corner:
C. Description of monument for corner and accessories established to	perpetuate locating the position of the corner:
K-8, 1/4 COBNER COMMON TO SEC. 23 & 24, T31N-R8W FD. 1/2" IRON ROD 33' EAST OF CENTERLINE N-S. GR. ROAD PULLED & REPLACED WITH ANTRIM COUNTY MONUMENT. FD. 1/2" IRON ROD ON W. ROW ROAD N83°W, 63.56' (R. 63.70') FD. 1/2" IRON ROD ON E. ROW ROAD S83°E, 2.34' (R. 2.30') SET NAIL ON SIDE 8" MAPLE, NO8°E, 37.42'. SET NAIL ON SIDE BLAZED 7" LOCUST, N80°E, 18.60'. SET NAIL ON SIDE 5" LOCUST, S57°E, 49.50'	Ratified by Peer Group in accordance with P.A. 345 Antrim Co. Chairman
SET NAIL ON SIDE BLAZED 10" LOCUST, \$18°E, 10.77'	Arthur L. Lennox Nov. 18, 1997
Signed by Kee Rach Kraf	Date
Surveyor's Michigan License No. 26460	