ARENAC COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

PE	المعادية والمساوية والأوار	괴	0.1	k ù	, E,

19 18 2 E 2000

For comment to	Filing Requir	ement of Act 74, Mich. P.A. 1	1970		JAN Z	5 2000						
For corners in	Landad Inc	0			SEC	MOIT						
ARENAC COUNTY (County)	Located In:	Corner Code #			J by W) [[1] (*** *********************************						
1. Public Land Survey	T <u>18N</u> R <u>5E</u> T R T R		AC CO. F		F DEEDS							
2. Property Controlling S in Section S	T R T R	RS Date 01 RECORDING	FEES:	0	Time 10	9.00						
3. Miscellaneous S	TR											
Property in Sec. S	T R		Register of Deeds Stamp & File Number									
4. Lot No, Recorded Pla	.+											
			1 A E	3 C D	E F C	HIJ	K L M					
5. Private Claims		· · · · · · · · · · · · · · · · · · ·	2	6 · <u> </u>	;	-32	1-1-					
			3	7	9	1011	12					
I, DALE L. WINIECKE , in			y 5									
state that under requirements of P.A. 74 lines 1 and 2 above were in conformant				 9 1 	71,5	 	13-					
current manual of survey instructions of the Management or by a decree of a Court of			.	<u></u>								
and 5 above were in conformance with t Decree of a Court of Law; established, re	· · · · · · · · · · · · · · · · · · ·		I .	92 	0 21	2223	24—					
below:		,	10	102	9——28—	272t	5 25					
NOTE: Not more than 2 corners, all in the	ne same Town and Ran	ge, may be recorded	11									
on this certificate.			123	[13] 3]	2——3'3—	3435	36-					
			131	I I								
A. Description of original monument	and accessories and/	or subsequent restoration:										
C-7 POST SET BY J. BURT, JULY 1843 10" ELM S45°E 31 LINKS 20" BLACK ASH N45°W 34 LINKS												
CERTIFICATE OF SURVEY, L. 1, P. 288, FLCRC, L. 1, P. 94, HERBERT L. FLUHART FIELD NOTES FROM WADE-TRIM/EDMAN 3/4" IRON.	Y, PS #18223, SEPTEM	MBER 1976, FOUND 1" BAR			°S#25835,	JUNE 1993,	FOUND					
B. Description of comer evidence to	ound and/or method a	pplied in restoring or reestablish	hing corne	••								
C-7		FF										
SEARCHED THE APPARENT LOCATION OF CHECKED WITNESSES, WITNESSES FROM SOUTHWEST CORNER OF HOUSE 113.35 EXCAVATED UNDER 1" BAR AND FOUNITHE 1" BAR IN THE CEDAR POST WAS A	M WADE TRIM FIELD NO 5' (R) 113.3' (M). S60° D CEDAR POST.	OTES: \$65°E TO NORTHEAST COI OW TO FACE OF POWER POLE 16:	2.35' (R) 16	2.3' (M)).	06.7' (M); S	47°E TO					
C. Description of monument for corr	ner and accessories e	stablished to perpetuate locatin	g the posit	ion of t	he corner:		• .					
C-7 REPLACED THE 1" BAR WITH 5/8"x 24" N52°W 31.20' TO NAIL AND TAG IN SO S68°W 162.55' TO NAIL AND TAG IN E/ S10°W 87.79' TO NAIL AND TAG IN WE S12°E 111.69' TO NAIL AND TAG IN EA N60°E 38.68' TO NOTCH IN WEST END	UTH FACE OF SOUTHE AST FACE POWER POLI IST FACE MAILBOX PO- IST FACE OF FENCE PO- 48" CMP	RLY TRIPLE ELM. E ST FACCEPIES BY	RETAINS COL	INTY ICIAL DON	TICE!	DALE WINIEC PROFESSIO SURVEYO	L. KE					
EAST 6' ± TO PHYSICAL CENTERLINE OF SOUTH 3' ± TO PHYSICAL CENTERLINE		No.1997	n Cios	63	200	No. 41915	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
() () · · · · ·	/		HAND REALIZOR	MAM!		POFECON	MALANAM					
Signed by Dale Mu	reell	1	Date 12	130/5	19	PANAL ESSIC	44444					
Surveyor's Michigan License No	41915			f f								