## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed on line and proportioned distance between section corners 1 /2 mile to east and west.

Found Wood post down at 37.64 chs. from west and is 35 links north of line. Aspen blazed in vicinity 13 years ago.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED \_\_\_\_\_\_ DATE \_\_April 23, 1963

REGISTERED LAND SURVEYOR
Billy D. Buckler