STATE OF MICHIGAN COUNTY OF BARRY RECEIVED FOR RECORD

## BARRY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

DEC 7 4 26 PM '93

Filing Requirement of Act 74, Mich. P.A. 1970

Sandy Schondelmarger REGISTER OF DEEDS

002127

Barry Located In: Corner Code =## T 1N R 7W G-5 **Public Land Survey** \_\_\_ R **Property Controlling** in Section 3. Miscellaneous Property in Sec.

For corners in

Register of Deeds Stamp & File Number

Recorded Plat Lot No. Private Claims

ı, <u>Daniel M. Ryan</u>, in a field survey on <u>September 8</u>, 19 <u>93</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

GLO: 14" Black Ash, S57°E, 18 links 18" Birch, N71°W, 33 links

Heath - 1903: 6" Black Ash, N17½°E, 1 chain, 25 links 10" Maple, N10½°W, 1 chain, 8 links Liber 3, Page 84 & 85

Found &" iron rod in monument box.

Northeast side U.P., Southeast, 130.19 feet North edge steel sign post, Southwest, 49.94 feet Centerline street sign, Northwest, 60.05 feet South edge sign post, Northeast, 55.31 feet

Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found  $\frac{1}{2}$  from rod in Monument box On centerline of M-66.

SURVEY & REMONUNENTATION

APR 0 5 1994

COMMISSION

Description of monument for corner and accessories established to perpetuate locating the position of the corner: Found ½" iron in monument box. Replaced with Barry County remonumentation iron & Chiseled "X" & drilled hole in top of concrete curb, N45°W, 50.71 feet Chiseled "X" & drilled hole in top of concrete curb, N55°E, 42.52 feet Chiseled "X" & drilled hole in top of concrete curb, S50°E, 51.23 feet Chiseled "X" & drilled hole in top of concrete curb, S44°W, 43.03 feet DANIE AE OF MICHIG DANIEL M. RYAN **PROFESSIONAL** SURVEYOR No. 34975 OFESSION

\_ Date \_

<u>September 8, 1993</u>