

MAY 2 2 1997

COMMISS DA

For corners in

BARRY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

COUNTY OF BARRY RECFIVED FOR RECOUR BEC 7 1 EE PM 193

STATE OF MICHIGAN

Filing Requirement of Act 74, Mich. P.A. 1970

ULL	J		ı	33 1 F	30
~	_	~			

Corner Code ## BARRY Located In: (County) A-13 (SW, 31) T 1 N R 10 W 1. Public Land Survey

Sandy Schondelmaryer REGISTER OF DEEDS

002095

Register of Deeds Stamp & File Number

2 3

12

		·	ETOTTTEATTE	
		T R		
		T R		
2.	Property Controlling	S T R		i
	in Section	S T R		Ì
3.	Miscellaneous	S T R		
	Property in Sec.	S T R		L
4.	Lot No,	Recorded Plat		

, David F. Peabody , in a field survey on _ September do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O.:

5. Private Claims __

W. Oak 9 N71E 69

10 N24W 27 Do

Resurvey By Cressy (Deputy Surveyor) 1884 Found Old Corner (Put in Tile) W. Oak 22 N881/2E 59

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G.L.O. & Cressy Witnesses were gone Found 3/4" Iron in 3" Tile (Slanted to North) 275' ± West of N1/4 Section 1, T.1S., R.11W. 1320' ± East of 1st Street

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" Iron W/Remon Cap in Center of Tile (Replacing Found 3/4" Iron) 2' ± N. of E & W Fence

In line with fence to North

20d Nail W/Barry Co. Tag, E. Side 7" Hickory S12°E 24.55'

20d Nail W/Barry Co. Tag, SE Side 15" Oak N42°E 33.10

20d Nail W/Barry Co. Tag, E Side 15" Oak N9°W 42.44'

20d Nail W/Barry Co. Tag, NW Side 18" Oak N70°E 62.24'



Signed by Daird	7. Peabody	Date
Surreyor's Michigan License No.	25866	CARL ADMINIST BY MICHIGAN CTATE