## BARRY COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

ELITHEY & REN UMENTATION

anne ka daa

<b>.</b>			1			Hr	K A.	* ZUU	U
For Corners in BARRY (county)	Located In:	Comer Code #		SECTION					
1. Public Land Survey NORTH 1/2 CORNER SECTION 1 BALTIMORE TOWNSHIP ON TOWNSHIP LINE 2. Property Controlling S in Section S	T_2N R_8W T_ R T_ R T_ R T_ R	L-1	a K. Burghdaff	- Barry		CRCR Is Stan			<b>1 of</b> 1999 09:0
3. Miscellaneous S_	T R			ΑВ	СД				
t, Brian Reynolds, in a field survey of P.A. 74, Michigan P.A. of 1970 conformance with regulations and instructions of the United States II a decree of a Court of Law and/or were in conformance with the rule of a Court of Law, established, reas expressed below.  NOTE: Not more than 2 corners, a	y on 14 AUGUST, 1998 do he, the corner points mentioned in the therefore as required in Department of the Interior, But that the corner points mentions of the Michigan Board of Lucatablished, monumented, retablished, and range	ereby certify that under require in lines 1 and 2 above were in the current manual of surviveau of Land Management coned in lines 3, 4, and 5 abound Surveyors or by a Decreption of the covered, for many be recorded on this cone.	e in vey or by vee ee found 1 tertificate, 1	1	5 - 8 - 17 -	<del>                                     </del>	-10- -15-	2-	12-
A. Description of original monu  1. THIS CORNER WAS NOT  2. COUNTY SHOWEN OF	I SET BY THE GENERA!	d/or subsequent restorati LAND OFFICE.		-					

- DUNTY SURVEYOR RECORDS: SETH PRATT, MARCH 1889 (L.2, P.265) "FOUND BY U.S. BEARING. PLACED POST 10 1/2LKS. EAST OF HASTINGS POST. MADE NEW BEARING " TAMARACK 18 N35 XW 21 1/LKS DEAD
- LAND CORNER RECORDATION CERTIFICATE: #238 BY MILTON E. DEKEYSER, P.S. #12019, 10 JUNE, 1975, "FOUND TILE AT FENCE CORNER W/ FENCE WEST, SOUTH AND SOUTHEAST (APPARENTLY SET IN RESURVEY, 1826)" NO WITNESSES GIVEN
- PRIVATE NOTES: FROM THE DEKEYSER FILES, P. McPHERESON, JUNE 1975, "TILE W/IRON IN FENCE CORNER. IN FENCE CORNER WITH FENCE SOUTH WEST & SOUTHEAST"

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND NO MAGNETIC EVIDENCE OF CORNER MONUMENTATION. FOUND FENCE CORNER IN SWAMP WITH DECAYING FENCES RUNNING EAST-WEST-SOUTHEAST AND 12'± WEST OF A BADLY DECAYING FENCE TO THE NORTH. EXTENSIVE EXCAVATION REVEALED NO EVIDENCE OF TILE OR IRON AS RECITED BY DEKEYSER OR MCPHERESON (ITEMS 3 & 4 ABOVE). TRAVERSED ALL OF SECTION 1, TYING OCCUPATION. FENCE CORNER IS ABOUT 2 FEET WEST OF MID-POINT BETWEEN K-1 AND M-1, AND ABOUT 8 FEET NORTH OF A DIRECT LINE. ACCEPTED FOUND FENCE CORNER AS BEST AVAILABLE EVIDENCE OF POSITION OF TILE AND IRON RECITED BY Dekeyser. Set standard barry county monument and cap at fence corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET STANDARD BARRY COUNTY REMONUMENTATION MONUMENT (3/4" X 36" IRON) WITH ALUMINUM CAP. SET 20d NAIL W/PLASTIC TAG IN THE WEST SIDE OF A 20" WILLOW N37°E 34.80' SET 20d NAIL W/PLASTIC TAG IN THE NORTHEAST SIDE OF A 4" ELM \$69°E 68.10' SET 20d NAIL W/PLASTIC TAG IN THE EAST SIDE OF A 10" POPLAR \$34°E 82.38' SET 20d NAIL W/PLASTIC TAG IN THE WEST SIDE OF A 10" POPLAR \$27°E 51.98" SET 20d NAIL WIPLASTIC TAG IN THE NORTHWEST SIDE OF A 12" WILLOW S26°W 80.48' CORNER LIES AT THE INTERSECTION OF DECAYING FENCES RUNNING SOUTHEAST / EAST / WEST L-13, T3N, R8W, LIES WEST 6.93'

ACT 345 BARRY COUNTY REMONUMENTATION APPROVED BY PEER REVIEW AT A MEETING HELD ON 8 June `9 £ BRIAN REYNOLDS

Date

Signed by

WICH10

BRIAN REYNOLDS

AND

MAYEYO

31602