

**Barry County Remonumentation  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

STATE OF MICHIGAN  
COUNTY OF BARRY  
RECEIVED FOR RECORD

DEC 9 3 02 PM '93

Sandy Schondelmarer  
REGISTER OF DEEDS

**002152**

Register of Deeds Stamp & File Number

Corner in  
Barry Co.  
(County)

Located In: Corner Code #  
Irving Twp. \_\_\_\_\_  
T 4N R 9W \_\_\_\_\_ G-5  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Public Land Survey

Property Controlling  
in Section  
Miscellaneous  
Property in Sec.

Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Robert Jonker in a field survey on Feb. 18, 1993  
hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.**

Description of original monument and accessories and/or subsequent restoration:  
LCRC #361, 1984, Donald L. Bissell P.S. #18655

4"x36" Conc. Monument - D.N.R.  
N60°W 10.79' 16" W.Oak  
N10°E 18.38' 12" R.Oak  
N45°E 26.63' 10" R.Oak  
S08°W 22.80' 16" R.Oak

SURVEY &  
REMONUMENTATION

APR 05 1994

COMMISSION


Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found conc. mon. per wit. listed in "A" above for LCRC #361

And is accepted as the best available evidence of the position of the  
original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
4"x36" conc. monument.

N60°W 10.79' 16" W.Oak  
N10°E 18.38' 12" R. Oak  
N45°E 26.63' 10" R.Oak  
S08°W 22.80' 16" R. Oak



Signed by Robert J. Jonker  
Surveyor's Michigan License No. #21572

Date 11/29/93