ONUMENTATION

APR 08 1996

Barry County Remonumentation

STATE OF MICHIGAN COUNTY OF BARRY RECFIVED FOR RECORL

Nov 20 8 35 AM '95

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich PA 1970

For corners in	rining nequ	mement of Act /4, whole F.A	Sandy Schoolshmaryer					
Barry	Located In:	Corner Code ≠#	REGISTER OF DEEDS					
1. Public Land Surve	T R T R		002317					
 Property Controlli in Section Miscellaneous Property in Sec. 	T R N T R N T R N T R N T R		Register of Deeds Stamp & File Number					
	, Recorded Plat		A B C D E F G H I J K L N					
	, in a field survey on August							
in lines 1 and 2 above current manual of surve Management or by a decapove were in conformal	der requirements of P.A. 74, Michigan P. were in conformance with regulations y instructions of the United States Deparee of a Court of Law and/or that the connec with the rules of the Michigan Boardhed, re-established, monumented, re-	and rules therefore as required in partment of the Interior, Bureau of La mer points mentioned in lines 3, 4 and d of Land Surveyors or by a Decree	the and 7 16 15 14 13 16 15 16 15 16 15 16 15 16 16					
NOTE: Not more the on this certification	an 4 corners, all in the same town icate.	and range, may be recorded	11 12 31 32 33 34 35 36					
A. Description of ori	ginal monument and accessories a	and/or subsequent restoration:						
•	t set by Lucius Lyons, DS 1826 S 32 W 27							

Beech 5N 52 W 20

1. Sylvester Sibley DS, 1830 (Barry Co. notes) Witness found to post set by Lucius Lyons

(Additional info. see back of sheet)

2. Barry County Road Comm. Stone

Iron post East 29.7' P.Pole N50°E 39.1'

SE cor. of foundation to church NW 68.31

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Found Capped rerod 1/2" x 18" A-3 SE cor. Hse. fndn. N30°W 89.0' C/L old iron post (Possibly old Street sign post) S50°W 46.10' Found Conc. Mon. East 33.05' C/L N-S bituminous Road C/L Gravel Road to West

ACT 345 BARRY COUNTY REMONUMENTATION APPROVED BY PEER REVIEW AT A MEETING HELD ON

COUNTY SURVEYOR **BRIAN REYNOLDS**

C.	Description of monument for corner and accessories established to perpetu-	ate lo	cating t	he position	of	the co	orner:
----	--	--------	----------	-------------	----	--------	--------

A-3	Replaced capped rerod with Standard Allegan Co. Mon. (3/4	I" x 24" Iron Rod with o	cap)				
	Nail & Allegan Co. Remon. Tag in NE side P.Pole	N 20° W	145.18'				
	Conc. Plat Monument	N 20° E	74.33'				
	SE cor. Hse. fndn.	N 30° W	89.0'				
	C/L old iron post (Possibly old Street sign post)	S 50° W	46.10' •				
	Found Conc. Mon.	East	33.05'				
	C/L N-S bituminous Road						
	C/L Gravel Road to West						
	A-3 corner is a common corner with M-3, Leighton Township, Allegan County.						

_ Date .. 39085 Surveyor's Michigan License No. _

KOERBER ROFESSION 39085 LAND SURVEYORS

3. April 27, 1972
Barry County road Comm.
Iron
Conc. Mon. East 33'
SW cor. Church N45°W 89.0'
UGC box N30°E 87.7'

May 26,1972
DeKeyser and Assoc.
Recorded survey L.1, Pg. 36, (Barry Co.)
Found 1" I.P.
SE cor. Church N45°W 89.60'
Util. pole East 22.47'

5. May 10, 1974
LCRC #176 (Barry Co.)
Found Iron pipe and brought to surface with 1/2" rerod
SE cor. Church fndn. N30°W 89.00'
Street sign S45°W 45.85'
Centerline road North & South
Tele. stanchion East 34.55'

August 9, 1977
Exxel Eng.
Recorded surveys, L. 1, Pgs. 408, 411,413,417, 986,987, 988 (Barry Co.)
Found capped DEK iron RLS# 12019
Rerod in conc. mon. E 33.0'
SE cor. Conc. bldg. fndn. NW 88.97'
NE. Edge street sign SW 46.05'

7. May 2, 1979
D.A. Ratekin & Assoc.
Recorded survey L.1, Pg. 556, (Barry Co.)
Iron Pipe
28" Oak N25°E 31.5'
6" Hickory N11°E 16.1'
P. pole S88°E 35.7'
8" Hickory S89°E 54.2'
Tele. pole S71°W 67.8'

1983 Jonker Land Surveys witnesses
Fnd. Capped rerod
SE Cor. former school hse.
fndn. N40°W 97.43'
Plat Mon. East 33.05'
C/L Street sign S50°W 46.2'

9. March 19, 1984
Exxel Eng. witnesses from
recorded survey (Allegan Co.)
Fnd. 1/2" Capped rerod
P.K. Nail in N. side wood post E 34.69'
W. cnd 18" CMP SSW 119.07'
Concrete Monument E 33.0'
SE Cor. Hse. Fndn. NW 97.50'

10. June 20, 1990
Exxel Eng.
Recorded surveys, L. 1, Pgs. 986,987, 988 (Barry Co.)
Found capped DEK iron RLS# 12019
Rerod in conc. mon. E 33.0'
SE cor. Conc. bldg. fndn. NW 88.97'
NE. Edge street sign SW 46.05'

11. July, 1991

MBN Eng./ Surv.

Recorded survey L.2, Pg. 46 (Barry Co.)

Found 1/2" Iron rod per LCRC 176.