ONUMENTAN

APR 0 8 1996

Barry County Remonumentation

Corner Code ##

STATE OF MICHIGAN COUNTY OF BARRY RECEIVED FOR RECORD

Nov 20 8 35 MM '95

COMMISSION

For corners in Barry

> Lot No. Private Claims _

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Sandy Schondelmaryer REGISTER OF DEEDS

	1000,	4N 10W	A-6(W 1/4, 18)			
1.	Public Land Survey	T R T R	Thornapple Twp.	002314		
		T R				
		<u> </u>				
2.	Property Controlling	S T R				
	in Section	S				
3.	Miscellaneous	S T R		Register of Deeds Stamp & File Number		
	Property in Sec.	S T R				
4.	Lot No.	, Recorded Plat		A B C D E F G H I J K		

, in a field survey on August Steven Koerber do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Located in:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

GLO (no post set)

No date

Barry County Road Comm.

Iron

Cor. iron post N45°W 40.11' Fence post S45°E 32.4' Fence Post S45°W 39.1' GR. Cable TR N45°E 45.11'

(Additional info. see back of sheet)

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Found Capped rerod 1/2"x18" A-6 Found 1 1/4" Iron Pipe South 2.67" Solid Iron rod North 1.23' Found 48" Stump S15°W 156.0'± Found MBT box (SE cor.) N45°W 45.8'

ACT 345 BARRY COUNTY REMONUMENTATION APPROVED BY PEER REVIEW AT A MEETING HELD ON

BRIAN REYNOLDS

COUNTY SURVEYOR

athining the state of the state

ion of monument	for corner and	accessories	established to perpetuate	locating the position	on of the comer.
i	on of monument	on of monument for corner and	on of monument for corner and accessories	on of monument for corner and accessories established to perpetuate	on of monument for corner and accessories established to perpetuate locating the position

A- 6	Replaced capped rerod with Barry Co. Mon. (3/4" x 24" Iron Rod with cap)			
4-0	Set 3/4" x 24" Iron rod with Allegan Co. Remonumentation witness cap	S 45° E		66.98'
	Set 3/4" x 24" Iron rod with Allegan Co. Remonumentation witness cap	N 50° E		58.20'
	Set 3/4" x 24" Iron rod with Allegan Co. Remonumentation witness cap	N 45° W		48.93'
	Set 3/4" x 24" Iron rod with Allegan Co. Remonumentation witness cap	S 50° W	Ī	46.45'

M-6, Leighton Twp., Allegan County, corner is South 2.90'

KOERBER ROFESSIONAL 39085

_____ Date _ Surveyor's Michigan License No. 39085

- 2. Nov. 29, 1977

 Exxel Eng.

 Recorded survey L.1, Pg.452, (Barry Co.)

 Bolt spike witnessed

 Nail & tag in N'ly side RR tie post SE 42.27'

 C/L MBT underground cable box NE 45.16'

 3/4" Iron (E 1/4 cor. Sec. 13) S 3.89'

 C/L Street sign N-NW 47,35'

 N. Edge Stop sign W-SW 50.94'
- 3. August 13, 1981
 LCRC #324 (Barry Co.)
 Paul Van Kooten
 Found capped iron on centerline of roads N-S-E-W
 Nail & tag in N. side corner fence post SE 41.75'
 1 1/4" Iron pipe S 2.65'
 SE corner MBT box NE 46.30'
 Nail & cap in SE side 38" Beech S-SW 155.66'
- 4. April 14, 1981
 Medema Van Kooten & Assoc.
 Recorded survey L.1, Pg. 691 (Barry Co.)
 Capped Iron
 Nail & Cap in side 38" Beech S-SW 155.66'
 SE cor. MBT Box NE 46.30'
- 5. Exxel Eng. notes
 Found MVK capped Iron Oct 1987
 Nail in N. side fence post SE 41.75'
 SE cor. MBT box NE 46.30'
 Nail in SE side 38" Beech S-SW 155.66'
 1 1/4" Iron S 2.65'
 Bt. spike N 1.20'
- 6. 1987
 Gackler Road Plans
 Barry Co. Rd. Comm.
 Note 3 corners in road used North corner
 Cor. Fence post N45°W 40.9'
 Cor. Fence post S45°E 32.3'
 Cor. Fence post S45°W 39.1'
 Tele. pole N45°E 45.9'