SURVEY & REMONUMENTATION

APR 23 1998


SECTION

REMON. COR. K-13, WILLIAMS TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION	Filing Requi	Filing Requirement of Act 74, Mich. P.A. 1970		
For corners in Bay		,	B RE AYE	
(County)	Located in:	Corner Code #	COUNTY OF THE PROPERTY OF THE	
1. Public Land Survey	T <u>14N</u> R <u>3E</u> T R T R T R	K-13	T 30 AN T 30 AN STER OF DEEL	
Property Controlling in Section	S T R		197 Ban IGAN	
Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number	
4. Lot No, Recorded I	Plat	*. * 		
5. Private Claims			_ ABCDEFGHIJKLM	
1. JERRY JONES in a field survey on July 18 19.97 do hereby certify			2 6 5 4 3 2 1	

I, <u>JERRY JONES</u>, in a field survey on <u>July 18</u>, 19 <u>97</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



- A. Description of original monument and accessories and/or subsequent restoration:
- K-13 Corner common to Sections 35 and 36 on south townline

Government survey, 1830's, set post Survey by Edmands Engineering, 1977, found iron, L-827, P-91 LCRC by I. McGinnis, 1972, found rerod, L-001, P-115 LCRC by J. Schafer, 1973, Found 3/8" rerod, set pipe, L-002, P-29 FROFESSIONAL SURVEYOR NO. 19838

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- K-13 Corner common to Sections 35 and 36 on south townline

Found 5/8" rod per survey by Edmands Engineer and LCRC's by L. McGinnis and J. Schafer

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- K-13 Corner common to Section 35 and 36 on south townline

Found 5/8" rod per surveys by Edmands Engineering and LCRC's by fL. McGinnis and J. Schafer, replaced rod with 5/8" rod and brass cap stamped Bay County Remonumentation, PS 19838, in mon box and is accepted as the best available evidence of the position of the accepted corner.

N 55 Deg E, 77.62', nail and disc in power pole (R)
N 60 Deg W, 51.43', notch in 24" CMP
S 70 Deg W, 52.12", chiseled "+" in 24" CMP
N 15 Deg W, 161.90', nail and Bay County disc in power pole

APPROVED LAND CORNER
P.A. 345 OF 1990 - Bay County
Date 27 June 97
M.T.M.
Michael MacDonald P.S.
County Representative

Surveyor's Michigan License No. 19838

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971



Revised Jan., 1983