SURVEY & BAY COUNTY REMONUMENTATION 1997 LAND CORNER RECORDATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

APR 23 1998

HLW .	
For corners in SECTION	
Located In: Corner Code #	K 😑
(County)	BAY DEC
1. Public Land Survey T 15N R 4E M-11	REG 9 (C GISTER COUNT
T_(15N_R_5E_(A-11))	FERRIT ID
TRTR	~ ~ <i>u</i>
2. Property Controlling S T B	ST ## 3.
in Section STR	EEDS %
3. Miscellaneous S T R Property in Sec. S T R	NAS S S S S S S S S S S S S S S S S S S
Property in Sec. S R	Register of Deeds Stamp & File Number
	The Number
4. Lot No, Recorded Plat	
5. Private Claims	A B C D E F G H I J K L
	2 - 6 - 5 - 4 - 3 - 2 - 1 -
Ronald C. Provost in a field amount of	3
I, Ronald C. Prevost , in a field survey on 5-14 , 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore	4 - 7 - 8 9 - 10 - 11 - 12
	5
a Court of Law and /or that the corper points mentioned in line 2.4 and 5 about or by a decree of	6 18 17 15 15 14 13
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	7
	8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9
on this certificate.	10 30 29 28 27 26 25
	11
	12 31 32 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	13
M-11 Post set by John Mullet, 1839. W. Oak 16 S.29 W 40 Lk.	
Y. Pine 18 N.75 W. 23 Lk.	
LCRC L2 P644, Hughes, 1989, fnd 3/8" I bar/mon box from prev. wil's. Act 132 L794 P27, McGinnis, 1976, fnd	
Corner M-11, T.15 NR.4 E., is common with A-11, T.15 NR.5 E.	
	e.
B. Description of corner evidence found and/or mothod applied in rectaring and a second a second and a second a second and a second a second and a second a second and a second a second and a second an	
and applied in restoring or reestablishing co	orner:
M-11 Found 3/8" rod in small mon box 5-14-97.	
Recovered two witnesses from L2 P644 that support position. Recovered two witnesses from L794 P27 that support position. (same)	
Measurement South 2648.52 agrees with previous w/t dist_2648.64/2648.5	
Measurement West 2629.69 agrees with previous w/t dist. 2629.78. Peer Group approval 7-31-97.	
Monument accepted as best available evidence of the position of the original corner.	
, amen or more original definer.	
•	
C. Description of monument for corner and accessories established to perpetuate locating the per	osition of the corner
M-11 Replaced 3/8" rod with 5/8" re-rod, Bay Co. bronze re-mon cap and	A STATE OF THE PARTY OF THE PAR
new mon box. 8-13-97.	STATE OF MICHIGAN
S.80°E. 69.93 ctr hyd (69.93 L2 P644)(70.00 L794 P27). S.50°E. 64.36 nail & cap S.W. face P. pole.	RONALD C.
S.25°W. 87.12 naif & cap S.E. face 30° Willow	* PREVOST *
S.65°W. 70.52 nail & cap N.W. face P. pole (70.52 L2 P644)(70.00 face L794 P27).	PROFESSIONAL
	SURVEYOR 5
	NO. 24612
$\bigcap M \cap \bigcap$	A POFESSIONAL S
Kma//// H-A	
Signed by Onald C. Viewov Date _/	<u> </u>
Ronald C. Prevost	·· ······
Surveyor's Michigan License No. 24612	

APPROVED LAND CORNER
P.A. 345 OF 1990 - Bay County
Date 3/ July 1/
Michael MacDonald P.S.
County Representation

County Representative

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED, MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

