APR 0 7 1998

## Remonumentation corner under P.A. 345, Michigan P.A. of 1990

Milliation corner and contractions	TELORTE
LAND CORNER RECORDATION CER	HIPICAIR
CALL TA Mich	D A 1978
Filing Requirement of Act 74, Mich. I	F.M. 1010

ALMIRA TWP. SECTION	LAND CORE Filing Requ	uirement of Act 74, Mich. P.A.	1970
For corners in		Corner Code#	LIBER 2 PAGE 155
BENZIE (County)	Located In:		STATE OF MICHIGAN  BENZIE COUNTY
1. Public Land Survey	T27NR 13W TR  TR	G1	RECORDED  19 Jan 1998 2:46:51 PM NICHELLE R. GRAY
Property Controlling     in Section	S TR S TR		REGISTER OF DEEDS H PAGES One
3. Miscellaneous Property in Sec.	s rR		Register of Deeds Stamp & File Number
requirements of P.A. 74, Michigan conformance with regulations and thinked States Department of the In-	n a field survey on Decemb- n P.A. of 1970, the corner points rules therefore as required in the sterior, Bureau of Land Managem	er 29, 19 97 do hereby certify that un s mentioned in lines 1 and 2 above wer current manual of survey instructions of ent or by a decree of a Court of Law and	the i/or 6 19 17 16 15 14 13 gan
Board of Land Surveyors or by re-monumented, recovered, found	as expressed below:	7/180 01	8 19 20 21 22 23 24
NOTE: Not more than 4 cor on this certificate.	ners, all in the same town	and range, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36 13
A. Description of original mo	nument and accessories and	d/or subsequent restoration:	and

August 1850 - GLO Surveyor - Set post and two

accessories: N41°E - 16.5' - Sugar 18"

N17°W - 13.2' - Lynn 6"

July 1973 - Carl Roser (DNR) - Found 1-1/4" Well Point and old remains of fence to North. Added DNR Monument and Cedar Guard Post. Four

accessories:

N88°W - 47,9' - Maple 12" N54°E - 34.5' - Maple 12" N40°W - 2.5' - Maple 14" S12°W - 18.0' - Ironwood 14" North - 2.5' - Fence (E-W)

October 1990 - Grand Traverse Surveying - Found

1-1/4" Well Point w/ DNR Cap and four

accessories:

N88°W - 47.9' - Maple 12"

N54°E - 34.5' - Maple 12" N40°W - 2.5' - Maple 14"

S12°W - 18.0' - Ironwood 14"

November 1996 - Gourdie Fraser & Assoc. J#960370 - Found DNR Monument and four

accessories:

N35°W - 2.85' - Maple 16" N15°E - 7.24' - Basswood 5" S20°W - 18.10' - Ironwood 18" N80°W - 48.21' - Maple 18"

Ratified by Peer Group In accordance with P.A. 345

Date.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

December 1997 - Gosling Czubak

Remonumentation - Found DNR Monument and well point on W side of Monument. Well point is I

1/4" x 3.8' iron pipe. The Benzie County Peer

Group accepted the position of the DNR Monument

for corner G1.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

December 1997 Gosling Czubak Remonumentation-

G1 (NE corner Section 4, T27N-R13W, Almira Twp.)

Set standard Benzie County Remonumentation Monument:

\$20W 18.10' to nail in 18" Ironwood

N80W 48.21' to nail in 18" Maple

N35W 2.85' to nail in 16" Maple N15E 7.24' to nail in 5" Basswood

N54E 35.29 to nail in 14" Maple

Matchen 42063 Surveyor's Michigan License No.

12-30-97

