RATIFIED BY THE BERRIEN COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 RECL.LJ OFFICIAL BERRIEN COUNTY REMONUMENTATION 00 SEP 13 PM 1:53 LAND CORNER RECORDATION CERTIFICATE BERNICE TRE THE WAY
REGISTER OF DEEDS
BERRIEN COUNTY. MICHIGAN For corners in Filing Requirement of Act 74, Mich. P.A. 1970 BERRIEN COUNTY..... Located in: ..HAGAR..... Township Corner Code # Public Land Survey T.3 S., R.18 W.M-6...... 09/13/00 111#1497 2. Property Controlling S...... T...... R..... E1/4 POST, SECTION 13 A66 T..... R..... CORNER in Section 09/13/00 \$7.00 S..... R..... 111#1497 Miscellaneous 866 STATE REMON FEE \$2.00 S..... T..... R..... Property in Sec. S..... T...... R..... Lot No., Recorded Plat Private Claims.... Register of Deeds Stamp & File Number I, George J. Mitchell....., in a field survey on ...July, 3, 2000..... do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3. 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed NOTE: Not more than 4 corners, all in the same town & range, may be recorded

Description of original monument and accessories and/or subsequent restoration: APRIL 1827 WILLIAM BROOKFIELD D.S. - SET POST AT 40 CHAINS NORTH OF SOUTHEAST CORNER OF SECTION 13.

APRIL 1894 LUTHER HEMMINGWAY, COUNTY SURVEYOR - FOUND STAKE AND ONE ORIGINAL BEARING TREE. SET NEW STAKE

NO DATE - BERRIEN COUNTY ROAD COMMISSION RECORDS- IRON BUT NO WITNESSES.

MAY 1976 MAURICE RUSHLOW P.S. - P. A. 132 SURVEY IN SE1/4, SECTION 13. FOUND 1-1/2" PIPE IN NORTH SIDE OF 26" POPLAR. WITNESSES: 6" TWIN MAPLE - NORTH - 11.97" (GONE), 8" MAPLE - WEST - 24.19" (GOOD), 8" OAK - N30"E - 17.58" (GOOD), W1/4 POST

Description of corner evidence found and/or method applied in restoring or reestablishing corner: B.

FOUND 1-1/2" PIPE IN NORTH SIDE OF TREE STUMP FROM CORNER HISTORY AND IS ACCEPTED AS A CAREFUL AND FAITHFUL

SET BERRIEN COUNTY STANDARD 1° BY 36" LONG PIPE INSIDE OF FOUND 1-1/2" PIPE. SET BRASS CAP WITH DRILL HOLE AND

THIS CORNER WAS APPROVED BY THE BERRIEN COUNTY SURVEYOR'S PEER GROUP ON JULY 6, 2000

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

EAST QUARTER POST OF SECTION 13, TOWN 3 SOUTH, RANGE 18 WEST. WITNESS TAG & NAIL IN WEST SIDE OF 27" OAK WITNESS TAG & NAIL IN SOUTH SIDE OF 14" MAPLE WITNESS TAG & NAIL IN NORTH SIDE OF 24" OAK AZ 180° 31.56 FEET WITNESS TAG & NAIL IN SOUTHWEST SIDE OF 28" OAK AZ 125° WITNESS TAG & NAIL IN SOUTHEAST SIDE OF 20" POPLARAZ 200° AZ 270° 25.11 FEET 19.84 FEET CORNER A-6, TOWN 3 SOUTH, RANGE 17 WEST 20.75 FEET 66.86 FEET AZ 180° 48.18 FEET

Lenge & Witchel Surveyor's Michigan Licerise No.19618..... SURVEY &

REMONUMENTATION

A.

JAN 31 2001

LIBER PAGE

