RACHTED BY THE BERRIEN COUNTY	
SURVEY PEER GROUP AS THE	George
OFFICIAL CORNER UNDER MICHIGAN	RECORDED
PUBLIC ACT 345 OF 1990 BERRIEN COUNTY REMONUMENTA	ATION
LAND CORNER RECORDATION CERTIF	EICATE
Filing Requirement of Act 74, Mich. P.A	UD MOST LA
Por corners in Located in: Corner Code #	SEQUIPE TALL
BÈRRIEN COUNTY PIPESTONE TWP. (M-11) NE COR. SEC. 36	BERNICE TRETHEWAY REGISTER OF DEEDS BERRIEN COUNTY, MICHIGAN
1. Public Land Survey T <u>5S</u> R <u>17W</u> M-11	BERRIEN COUNTY, MICHIGAN
1. 1 dono Edita Od. 403	
TR	
$\frac{T}{R} = \frac{R}{R}$	
2. Property Controlling S T R	•
in Section S T R	
· · · · · · · · · · · · · · · · · · ·	ster of Deeds Stamp & File Number
Property in Sec. S T R	
4. Lot No,Recorded Plat	
5. Private Claims	A B C D E F G H I J K L M
2	6 + 5 + 4 - 3 - 2 + 1 -
3	
I, Alan Bartlett in a field survey on November 13, 1998 hereby certify that	7 - 8 - 9 - 10 - 11 - 12 -
under requirements of P.A. 74, Michigan P.A. of 1970, the corner points	
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the	
United States Department of the Interior, Bureau of Land Management or by	19 + 20 + 21 + 22 + 23 + 24
a decree of a Court of Law and/or that the corner points mentioned in lines 3,	
4 and 5 above were in conformance with the rules of the Michigan Board of	30 - 29 - 28 - 27 - 26 - 25
Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	
12	2 31 + 32 + 33 + 34 + 35 + 36
NOTE: Not more than 4 corners, all in the same town and range, may	
be recorded on this certificate.	11/19/98 111#6180 A77
	CORNER \$9.00
	11/19/98 111#6180 A77
A Description of ariginal many many and account account and account account and account account account and account account and account account account and account account and account accoun	STATE REMON FEE \$2.00
A. Description of original monument and accessories and/or subsequent restoration:	800000
	REMONDATION
(DI FACE OFF BACK BACE)	
(PLEASE SEE BACK PAGE)	JAN 12 <sub>1889</sub>
	SECTION
B. Description of comer evidence found and/or method applied in restoring or reestablishing co	
, and the same state of the sa	and.
Found Dinah Dina in Management Day 01) Mart of October 17 10 11 17 15 15	
Found Pinch Pipe in Monument Box 3' West of Center Line and Center Line of Eurel Witnesses. This Government Monument was restored with approval of the Berrien County	Ka Extended. Verified Corner using existing
on October 6, 1998.	remonumentations real cloup of curveyors
	·
C. Description of monument for corner and accessories established to perpetuate locating the	position of the corner:
Set 3' long steel pipe with 3½" dia Berrien County Remonumentation cap in Monun	ment Box 3' West of Center Line and Center
Line of Eureka Road extended.	
Witnesses N30W Set Nail and Flasher in NE face P.P. 45.95'	
N75E SW Corner of Concrete Block Building 46.52'	
S30E NW Corner garage addition 77.70'	
S35W Set Nail and Flasher in NW face 36" Oak 61.11'	
Corner is accepted as a careful and faithful perpetuation of the position of the original corner.	11 01 11/6
A U D All . l. la	ALAN LOW
Signed by Surveyor's Michigan License No. 35988	LAND LAND
Surveyors Michigan License No. 35988	SURVEYOR No.
	35988
	The Ca Thomas of the Care

LIBER 4PAGE 110

## M-11 NE CORNER SECTION 36, SE CORNER SECTION 25 T5S, R17W PIPESTONE TWP.

		•			1	9
March 1827	GLO William Broo	kfield	Book 1	Page 107 of F	ield Notes	
	North on East side of	Section 36	3			
	80.00 Set Cor to Se	Witness	ses	30, 31.		
	W. Oak 20 "do" 12	N541/2\ S23 2/3		10 Lks 78 Lks		
BCRC	no dates					
	Iron	Witness	243			
	20" W.Oak	N30E	,,,,	74.4'		
	14" Hickory	S85E		33.4'		
	6" Walnut	N25W		75.4'		
	14" R. Oak 8" Hickory	S30W S45W		60.9' 50.5'		
	Fence Post	East		28.5'		
•	NE Corner to N 1/4 C	orner=	2623.3			
J.H.Dewey	Misc. Field Notes (no	o dates)			•	
·		Witness	es			
	SW Cor Bldg		46.5'			
* · · · · · · · · · · · · · · · · · · ·	P.P. 24" Oak	N40W S30W				
	L'I Ouit	00011	00.2			
July 1972	Wightman and Asso Found Iron Pipe			t RLS #16039	Recorded Survey Lit	per 936 Page 49
4	C) // C = " Did="	Witness				
	SW Cor Bidg Power Pole	N70E N40W				
	24" Oak	S30W				
July 1974	<b>Wightman and A</b> sso Pinch top Pipe	c. Richard	i Garret	t RLS #16039	Recorded Survey Lik	per 981 Page 303
	014.0 514	Witness				
grade and a second	SW Cor Bldg		46.51'	•		•
•	Utility Pole 18" Oak	N30W S45W	60.03	·		
July 1975	Wightman and Asso NE Corner of Sec 36				Recorded Survey Lib	oer 1004 Page 108
Aug 1975	Wightman and Asso Found Iron Pipe	c. M.R. Rı	ushlow	Ris #15191	Recorded Survey Lib	per 1006 Page 764
· · · ·	•	Witness				
	SW Cor Bldg	N65E				
	Utility Pole 18" Oak	N30W S45W				•
	10 Cak	07011	00.00			
1978	Wightman and Asso Iron Pipe			RLS #15191	Survey Certificate	
	SW Cor Bldg	Witness N65E				NUMENTON
	Utility Pole					·
	18" Óak	S45W			J.L	in 12 <sub>1999</sub>
•	3' West of C/L	Road				
March 1978	Robert Prestine RLS Iron Pipe		_	Certificate	ξ	ECTION
* _ *	SW Corner Building	Witness N65E				
	P.P.	N30W				
	18" Oak	S45W		:		
1998	Landmark Technolog	gies .	Alan Ba	artlett RLS # 35	5988	
	Found Pinch Pipe in M	lon. Box. 3 Witness		of Center Line a	nd Center Line of Eurek	a Extended
		ail and Flas	sher in 1	N.E. face of P.P.	. 45.95'	
-				ck Building	46.52'	
		orner of Ga		ddition VW face 36" Oa	77.70' k 61.11'	
	30011 Set 14	un unu 1 168	51101 H1 I	177 IUOG 00 Od	N VI.II	

LIBER 4 PAGE 111