PK in PP N25d34'W 76.74 Hydt N28dW 60.70'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

in Monume. 1" Pipe 36" Long with 2½" Remonumentation Brass Cap in Monument Box ANTE OF MICHIGA

Witness Tag in PP N89d27'E 32.3' Witness Tag in PP S68d55'W 55.51' Witness Tag in PP N25d34'W 76.74' Hydt N28dW 60.70'

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSISSION OF

Signed to Unique so W. Bayer REMOVIMENTE TON 31589

Date <u>OCTOBER 26, 2000</u>

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

JAN 31 2001

LIBER 4

PAGE 234

## 2000 Berrien County Remonumentation Barger Engineering, Inc.

## NORTHWEST QUARTER CORNER SECTION 11, T5S, R19W NORTHEAST QUARTER CORNER SECTION 10, T5S, R19W I-3

Feb. 1830

L. Lyons

Set Post

B Oak 14 S12W 14

Pine 10 N82E 14

Feb. 1876

T. Love

Large Stone

w/three small stone about it

B Oak 6.2 S11E 2.2 1/2

1973

Berrien Co. Rd Comm

Set Iron

Concrete Monument East 33.0'

PP S88E 31.8'

14" Maple S30W 40.0'
PK in PP N20W 76.0'
PK in PP S70W 54.72'
Top Nut in Hydt N28W 60.8'
10" Maple S35d53'E 42.4'
8" Maple S34W 40.1'

6" Cedar N57 1/2W 28.4'

Jan. 1976 Wightman

Survey - Found Monument Box

12" Maple S35W 40.55'

PP East 32.2' Hydt N30W 60.65'

Apr 1987

Survey - Found 1" Iron in Monument Box

J. Kamer

PK in PP N45W 76.41'
PK in PP S80W 55.17'
PK in PP East 32.15'
33' S of C/L Trafalgar Drive

Jan 1992

Recorded Corner

R. Harner

Found 1/2" Iron in Monument Box

PK in PP East 32.15' PK in PP N30W 76.41' PK in PP S80W 55.18'

June 2000

Found 5/8" Iron in Monument Box

C. Barger

PK in PP N89d27'E 32.3' PK in PP S68d55'W 55.51' PK in PP N25d34'W 76.74'

Hydt N28dW 60.70'

Barger Engineering, Inc. 20249.02

SURVEY & REMOVIMENTATION

JAN 31 2001

LIBER 4 PAGE 235

SECTION