AUTOUR THE BERREN COUNTY	RECORDED
SURVEY PEER GROUP AS THE FFICIAL CORNER UNDER MICHIGAN BERRIEN COUNTY REMONUM LAND CORNER RECORDATION C Filing Requirement of Act 74, Michigan BERRIEN COUNTY REMONUM LAND CORNER RECORDATION C Filing Requirement of Act 74, Michigan BERRIEN COUNTY REMONUM LAND CORNER RECORDATION C	ERTIFICATE h. P.A. 1970 98 NOV 19 PM 4:48
For corners in Located in: Corner Code #	GERNICE TRETHEWAY REGISTER OF DEEDS BERRIEN COUNTY, MICHIGAN
BERRIEN COUNTY BERTRAND TWP. (B-9) S1/4 Sec 19 (State Line)	•
1. Public Land Survey T_8S_ R_17W B-9	
T R	Register of Deeds Stamp & File Number
2. Property Controlling S T R	11/19/98 111#6180 A77
in Section S T R Solution S T R Property in Sec. S T R	CORNER \$7.00 11/19/98 111#6180 A77 STATE REMON FEE \$2.00
4. Lot No,Recorded Plat	
5. Private Claims	A B C D E F G H I J K L M
	2 6 5 4 3 2 1 1
	4 7 8 9 9 10 - 11 - 12
I, <u>Alan Bartlett</u> in a field survey on <u>November 13 1998</u> hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points	5
mentioned in lines 1 and 2 above were in conformance with regulations and	6 18 17 18 15 14 13
rules therefore as required in the current manual of survey instructions of the	8 - 19 - 20 - 21 - 22 - 23 - 24
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3,	9 4 1 1 1 1 1 1 1
4 and 5 above were in conformance with the rules of the Michigan Board of	10 - 30 - 29 - 28 - 27 - 26 - 25 -
Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	11 12 31 - 32 33 34 35 36
monumented, re-mondimented, recovered, round as expressed below.	13
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	SURVEY & REMONUMENTATION
A. Description of original monument and accessories and/or subsequent restoration:	JAN 12 1939
(No Government Corner Set)	ANN TE GOOD
B. Description of corner evidence found and/or method applied in restoring or reestablish	shing corner: SECTION
No Government corner set. Used Michigan Department of Transportation notes corner on state line as determined by existing Indiana corners. Government Mor Remonumentation Peer Group of Surveyors on November 10 1998.	
C. Description of monument for corner and accessories established to perpetuate location	ing the position of the corner:
Set Concrete Monument with Berrien County Remonumentation Cap in corn Witnesses	field. 50' South of west running fence.
S80E Set Nail and Flasher in 9" Clump Mullberry	76.94'
West Fnd 1" Iron Pipe	47.63'
N40W Notch in R.R.Rail fence Post N.E. side N75W Set Nail and Flasher in N side of 36" Tree	66.00' 44.92'
Server and I wone in 14 and a feet for	
This position not established by original government surveyors. This monument is ac the corner.	cepted as the best available evidence of the position of

Signed by Surveyor's Michigan License No. 35988

4PAGE 114

LIBER