				O SRECORI	1	\bigcirc
	BY THE BERRIEN COUNTY			- militari	<i>,</i>	
SURVEY FFICIAL C	PEER GROUP AS THE ORNER UNDER MICHIGAN				++t .	٠
MBLI	C ACP 345 OP 1990	PEDDIEN COUNT	Y REMONUMENTATION	SEGRATIC IS A	M Q: 20	
	5 Que	LAND CORNER RE	CORDATION CERTIFIC	CATE		
Forcome	-04-99	Filing Requirement	t of Act 74, Mich. P.A.	1970 ERNICE TRET REGISTER OF	HE WAY DEEDS	
		•		BERRIEN COUNTY.	MICHIGAN	
Berrien	(County) Located	In: Corner	Code #			
1. Public	Land Survey T <u>8</u>	S R 20W	К-9			
	<u>T</u>	R				
	<u> </u>	R	· 	08/16/99	111#9898	A99
	erty Controlling S T T				CORNER	\$7.00
in Sec 3. Misce	ellaneous S T _	R		08/16/99	111#9898 STATE REMON FEE	499 00 cs
Prope	erty in Sec. S T	R		•	DIHIE KEMUN FEE	. PZ.UU
4. Lot N	o, Recorded Plat			Register of D	eeds Stamp & File N	umber
5. Privat	e Claims		3	ABCD	e f G H I J	K I. M
				1 1		
	:			2 - 6 - 5 -	432	
				4 7 8	91011	12-
I, <u>V.J. S</u>		in a field survey or	16 June	5		
points mer	do hereby state that under requirentioned in lines 1 and 2 above were in	conformance with regula	tions and rules therefore as	61817	16 15 14	13
Bureau of	the current manual of survey instruction Land Management or by a decree	of a Court of Law and	/or that the corner points	7		
Land Surv	in lines 3, 4 and 5 above were in c eyors or by a Decree of a Court	onformance with the rule of Law; established, re	s of the Michigan Board of established, monumented,	8 19 20	21 22 23	24-
recovered,	found as expressed below:			9		
	lot more than 2 comers, all in the sai	ne town and range, may	be recorded	10-3029-	282726-	25
	on this certificate.		!	11 31 32	33 34 35	36
A. Desc	ription of original monument and	accessories and/or sub	sequent restoration:	13		30-
	· -	400000000000000000000000000000000000000	in the state of th			
1830	LUCIUS LYON, D.S. SOUTH BETWEEN SECTIONS 2		TO SOUTH BOUNDARY			
	4.96 CHAINS EAST OF 12 MIL 4" ELM N 34° E 23 LINKS.	POST.		·		•
	6" WHITEWOOD N 54° W 45 L	INKS		•		
1886	ALBERT L. DREW, COUNTY SU		LDER HENRY			
	STAKE WITH STONES AROUNI 6" WHITEWOOD N 54° W 45 L		3			
1990	WIGHTMAN & ASSOCIATES, II	ıc ·	DEC 2 3 1999	3		
	FOUND STONE AT FENCE COR	NER			MINIMINING THE PARTY OF MANAGEMENT	.
:	PK NAIL IN 20" OAK N 40° E 9 PK NAIL IN 12" OAK SOUTH 5.	25'	SECTION		HILLE OF MICA	3/1/2
* * * * * * * * * * * * * * * * * * * *	PK NAIL IN 10" MAPLE S 40° E PK NAIL IN 8" OAK S 30° W 20				G V.J.	是是
	FOUND STONE AT FENCE COR				PROFESSIONAL	
					SURVEYOR NO.	23
B. Desc	ription of corner evidence found	and/or method applied	in restoring or reestablish	ning corner:	26469	E. E.
16 IUNE	1999 - WIGHTMAN & ASSOCIA	TES INC FOUND STO	NE AT EENCE CORNER		POPESSIONAL S	III.
10 30142	1999 - MIGHTIMAN & MOOOÇIA	123, 1140. 1 00110 310	INC AT TENCE COMMEN.		AMMINIO.	
		•				
			į			
C.	Description of monument for co	rner and essective as	stablished to mare etcet-	anatina the masitis	of the country	
			stablished to perpetuate i	ocaling the position	or the comer;	
SEI 4" X	3' CONCRETE MONUMNET W/B	.C.R.P. BRASS CAP				4,
	IN 16" WALNUT N 60° E 9.57' IN 12" MAPLE S 30° E 24.05'					
WIT TAG	IN 10" WILLOW S 10° E 6.06'	· ·		•	,	
FOUND R	IN 8" WILLOW S 40° W 20.82' EBAR WEST 330.62'				_	
FOUND S	TONE WEST 326.87'			·		
AND IS A	CCEPTED AS A CAREFUL AND F	AITHFUL PERPETUATI	ON OF THE POSITION OF	THE ORIGINAL CO	RNER	
-	1			. ,		
Signed by	- Led A			Date 5/	MG. 1999	1
	Michigan License No. 26469		• 1			
			FORM APPROVED BY	MICHIGAN STATE BOARD OF I	PROFESSIONAL SURVEYORS JAK	J 28 1971

STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1996

4 PAGE 149

lirer