

**SURVEY & REMONUMENTATION**

**MAR 13 1998**

**SECTION**

**BRANCH COUNTY REMONUMENTATION CORNER  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

<u>BRANCH</u>	Located In:	Corner Code #
(County)		
GIRARD TWP.		
1. Public Land Survey	<u>T 5 S R 6 W</u>	<u>E-7</u>
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

STATE OF MICHIGAN  
Branch County  
Recorded

10-22-1997 09:56:15

Linda Lee Morrison-Mathews  
REGISTER OF DEEDS

Liber **00003** Page **0161**

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, EDWARD W. REED, in a field survey on SEPTEMBER 9, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:  
1825: R. CLARK jr, DEPT. SURVEYOR - CORNER SET  
1991: DAVID MOSTROM, SURVEYOR - CORNER LOCATION FALLS IN CUT AREA IN ROADWAY, SET 1/2" X 24" CAPPED IRON IN CI-MONUMENT BOX DOUBLED OVER LINE & DISTANCE FROM N 1/4 CORNER AND NE CORNER. RECORDED IN LCRC # III-132

ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON

9-10-97  
E. R. Reed, P.S. Co. Rep.  
**E.R. REED**

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" IRON ROD IN CI-MONUMENT BOX FITTING WITNESS OF LCRC # III-132

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET REMON CAP ON EXISTING IRON ROD IN CI-MONUMENT BOX  
NAIL & FLAGGING IN T. POLE, N49E 51.74'  
NAIL & FLAGGING IN T. POLE, S60E 41.39'  
NAIL & FLAGGING IN T. POLE, S79W 85.39'  
C/L ROADWAY, NORTH 9.0'  
NW CORNER CONCRETE ANCHOR POST, SOUTH 26.59'

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER

Signed by Edward W. Reed  
EDWARD W. REED

Date SEPTEMBER 9, 1997

Surveyor's Michigan License No. 33985

