## SURVEY & REMONUMENTATION

MAR 1 3 1998

## SECTION

MONUMENT BOX:

North 28.91 - Steel corner Post.

N25E 36.5' - Center of 36" Walnut stump. S50E 32.2' - Center of 18" Wanut.

S45E 32.3' - NW corner square concrete anchor post.

S45W 33.4' - NE corner square concrete anchor post.

In line with fenceline running North & center of roads E-W-S.

## BRANCH COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		i iiiig ricquirei	none of Aut 1-1, mione i	
BRANCH	tinca	ted In:	Corner Code ##	STATE OF MICHIGAN
(County) UNION TO			000.0000	Branch Counts Recorded
Public Land Survey	ÿ T. <u>.</u> T	5 S R 7 W R R	<u>I ~ 8</u>	10-22-1997 09:59:02 Linda Lee Morrison-Mathews
<ol> <li>Property Controllin in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	s T _ s T _ s T	R R R R R		REGISTER OF DEEDS Liber UUUU3 Page 0184 Register of Perphysiamp & File Nember
				UNION TOWNSHIP
Lot No      Private Claims				A B C D E F G H   J K L  2 6 5 4 3 2 1 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1
do hereby certify that und in lines 1 and 2 above w current manual of survey Management or by a decrabove were in conforman Court of Law; establish expressed below:	er requirements of P.A. were in conformance we instructions of the Un- ee of a Court of Law and ce with the rules of the ed, re-established, in the corners, all in the ed.	. 74, Michigan P.A. o vith regulations and lited States Departm d/or that the corner e Michigan Board of nonumented, re-mo	7, , 19 97 f 1970, the corner points ment rules therefore as required nent of the Interior, Bureau of points mentioned in lines 3, 4 Land Surveyors or by a Decre onumented, recovered, four	ioned in the Land 7 and 5 8 19 20 21 22 23 24 10 as 10 30 29 28 27 26 25
on this certific	ate.			13 32 33 34 35 36
G.L.O. FIELD witness BENNETT, 187 M. KNOWLES, E.R. REED, O pin" B	ONOTES: R. Clar ses-now gone). 4: "Fd US tree Dep. Co. Surve Co. Surveyor, Catablished Wit	rk, Dep. Surve, planted pleyor: "Fd sto 1970: "Found tnesses to co	brick but no stone	Itr sec post," (3
B. Description of corr	ner evidence found	and/or method ap	plied in restoring or reest	ablishing corner: జుద్దమ్ముల్లో జుద్దమ్ముల్లో
From prior set.	wijnesses I us	ed in 1970,	I dug and found t	he 3/4" x 18 steel particular
Branch Count	_	tion Cap on t	op and placed same	eel rebar rod set in concrete with in a C-I monument box.
	PTED AS A CARE	EFUL AND FAIT	HFUL PERPETUATION	OF THE POSITION
				ocating the position of the corner:

EDWARD R

REED