REMONUMENTATION

FEB 13 2001

BRANCH COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Branch County

Q	C	~	Т	н	\cap	١	LΚ
J		C	ı	и	U	ļ	V

Miscellaneous

Property in Sec.

For corners in Corner Code ## Located In: BRANCH QUINCY TWP. A-05 T 6 S R 5 W 1. Public Land Survey __ R _ _ R _ R , R 2. Property Controlling _ R _ Т S in Section

Τ.

S

STATE OF MICHIGAN Recorded

12-15-2000 14:08:14

Linda Lee Morrison-Mathews REGISTER OF DEEDS

Liber OOOO Page 0131

Register of Deeds Stamp & File Number

QUINCY TWP., T6S, R5W

__ , Recorded Plat _ Lot No. 5. Private Claims,_

R_

__ R

EDWARD R. REED, P. Sn a field survey on OCTOBER 25, 2000 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

SECTION CORNER COMMON TO SECTIONS 7 & 18, ON THE WEST LINE OF QUINCY TWP.:

1829 - G.L.O. FIELDNOTES OF ORANGE RISDON, D.S.: "WEST BETWEEN SEC'S 7 & 18....80.00 INTERSECT W BDRY 35 LKS N OF POST. SET POST COR SEC'S 7 & 18".

1878 - M. KNOWLES, CO. SURVEYOR: "FOUND STONE. SET STONE 24 AND BRICK".

1999 - L.C.R.C. 4/37 BY E.R. REED, COUNTY SURVEYOR: FOUND A C-1 MONUMENT BOX WITH NOTHING IN IT; FURTHER, I HAD PREVIOUSLY OBSERVED SAME MONUMENT BOX WITH A CAPPED IRON ROD IN SAME. FRED CUTCHER, P.S. #24592 STATED THAT HE HAD FOUND THE BOX WITH A SQUARE IRON BAR IN SAME ON A PREVIOUS OCCASION.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

AS DESCRIBED BY L.C.R.C. 4/37, I FOUND A 1/2" REBAR IRON IN THE MONUMENT BOX. PLACED A BRANCH COUNTY REMONUMENTATION CAP ON THE REBAR;

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON

Z.P. Red E.R. REED, CO.REP.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

BRANCH COUNTY REMONUMENTATION CAP, ON REBAR, IN C-I MONUMENT BOX:

N 55 W 54.5' - CENTER OF 26" MAPLE.

S 30 W 52.10' - NE CORNER OF SQUARE CONCRETE POST.

SOUTH 24.5' - CORNER MONUMENT TO COLDWATER TWP., SECTIONS 12/13.

SOUTH 12.7' - CENTERLINE OF STATE ROAD PAVEMENT.

TO THE STOR BRANCH THE DEPARTMENTAL MAP A PURPOSES ONLY THIS MY NOT TO BE REPRODUCED SEND PUBLIC TO REGISTER OF DEEDS FOR COPIES.

Date OCTOBER 25, 2000

Signed by _

Surveyor's Michigan License No. 7437

REED PROFESSIONAL

OF MICHI

EDWARD R.

PESSION!

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAH. 28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983