SURVEY & REMONUMENTATION

_____, Recorded Plat

BRANCH COUNTY REMONUMENTATION. CORNER *

LAND CORNER RECORDATION CERTIFICATE Liber 00003 Page 0062

MAR 2 1 1997 Filing Requirement of Act 74, Mich. P.A. 1970

i ming requirement of Act 14, mich. F.A. 15				M. 1370
	BRANCIMMISSION ICOUNINI COLDWATER TWP.	Located In:	Corner Code ##	STATE OF MICHIGAN "Branch County Recorded
1.		T <u>6 S R 6 W</u> T R T R T R	B - 05	10-30-1996 09:13:45 Linda Lee Morrison-Mathews
2.	Property Controlling S in Section S	T R T R		REGISTER OF DEEDS
3.		T R T R		Register of Deeds Stamp & File Number

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

_RXXXX

4. Lot No. ______

5. Private Claims ___

QUARTER CORNER TO SECTIONS 7/18, T6S, R6W, COLDWATER TWP.

G.L.O., W. BROOKFIELD, D.S. 1825: "SET QTR. SEC. POST AT AVER. DISTANCE."
G. E. ANDERSON, MSHD, 1970: "RE-ESTABLISHED (corner) ON LINE AND MIDWAY BETWEEN
N.W. CORNER 18 AND N.E. CORNER 18. SET 3/4" PIPE."

E. R. REED, CO. SURVEYOR, 1987: FD. PIPE. RECORDED L.C.R.C. 2/104

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Notes of G. E. Anderson, Survey Chief, MSHD, (now MDOT), 9-16-70: "Dug hole 8' wide all across road; Found nothing. Re-established on line and midway between N.W. Corner 18 and N.E. corner 18. Set 3/4"x32" Pipe in Mon. Box. Corner fell 2' West of Fence line North and 3½' west Fe line South. also fell on South edge Hurley Road."

From Anderson's witnesses, I uncovered and used this corner on Sept. 11, 1987, and recorded L.C.R.C. 2/104.

This date, August 19, 1996, I again uncovered this corner and set a Branch County remonumentation cap on a $\frac{1}{2}$ "x18" rebar rod cemented inside the existing pipe.

And is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

BRANCH COUNTY REMONUMENTATION CAP, ON REBAR ROD IN PIPE. IN CI MONUMENT BOX:

9.5 ft. SOUTH OF C/L HURLEY ROAD. 22" HICKORY- SOUTH 24.58'TO CENTER. 30" HICKORY- N 65 E 69.90' TO CENTER. NW CORNER CONCRETE POST- S 10 E 17.43' SW CORNER CONCRETE POST- N 05 E 35.52'

12" HICKORY- S 55 W 41.60' TO CENTER.

11

12

COLDWATER TWP.

16" HICKORY - N 30 E 39.05' TO CENTER.

18" OAK- N 14 E 36.75' TO CENTER

ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON

Date AUGUST 19, 1996

EDWARD
R. REED
LAND
SURVEYOR
NO.
7437

Signed by EDWAR Surveyor's Michigan License No.

7437

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983