## SURVEY & REMONUMENTATION

MAR 2 1 1997

COMMISSION

BRANCH COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE LIBER 0003 Page 0068

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in "STATE OF MICHIGAN Branch County BRANCH Located In: Corner Code ## Recorded. COLDWATER TWP. T 6 S R 6 W 1. Public Land Survey 10-30-1996 09:18:55 T \_\_\_\_\_ R \_\_\_\_ \_\_ R \_ Linda Lée Morrison-Mathews T \_\_\_\_\_ R \_\_ REGISTER OF DEEDS 2. Property Controlling \_ T \_\_\_\_ R \_\_ S \_\_\_\_ R \_\_\_\_ in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. \_\_ , Recorded Plat \_\_ 5. Private Claims \_ AUGUST 12 I Fäward W. Reed  $\_$  , in a field survey on  $\_$ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 13 QUARTER CORNER COMMON TO SECTIONS A. Description of original monument and accessories and/or subsequent restoration: 1829: O. RISDON, DEP. SURVEYOR, CORNER SET 14 & 15, T6S, R6W, COLDWATER TWP. F. SOLL, STATE SURVEYOR, FOUND STONE ON END WITH BRICK AT ITS NORTH SIDE, POINTED STONE AND BRICK IDENTIFIED IN PREVIOUS RESURVEY FROM ORIGINAL GOVERNMENT SURVEY, SET STANDARD MI E.R. REED, COUNTY SURVEYOR, FOUND IRON BAR 1979: D. BEVER, M.S.H.D. SURVEYOR, FOUND RR SPIKE OVER REMAINS OF OLD S.M.M., SET 3/4" PIPE 1985: IN CAST IRON BOX, RECORDED L.C.R. #II-0077 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND 3/4" PIPE & CAP IN CAST IRON BOX REMOVED PIPE AND SET 1/2" X 12" REBAR IRON AND REMONUMENTATION CAP D BY THE BRANCH COUNTY PEER GROUP AS THE OFFICIAL UNDER MICHIGAN PUBLIC ACT 345 AT A MEETING HELD ON C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: OF HICH 1/2" x 1.2" REBAR WITH REMONUMENTATION CAP IN CAST IRON BOX N45E 92.83' TO CHISELED "+" IN S BASE STEEL LIGHT POLE N65W 137.00' TO CHISELED "+" IN S BASE STEEL LIGHT POLE **EDWARD** W. REED \$75W 240.45' TO NE CORNER MICHIGAN STATE POLICE BLOCK BUILDING N89 degrees 56' 30" E 2669.63' TO SE CORNER SECTION 10, T6S, R6W LAND S68E 98.7' TO NAIL & TAG 2' UP WEST SIDE OF POWER POLE SURVEYOR SOSE 45.1' TO FACE OF TELEPHONE PEDESTAL NO. \$82W 106.7' TO FACE OF TELEPHONE PEDESTAL 33985 And is accepted as a careful and faithful perpetuation of the position of the original corner. Date \_\_\_\_\_AUGUST 12, 1996 Edward W. Reed 33985 Surveyor's Michigan License No. . FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971