SURVEY & REMONUMENTATION

MAR 1 3 1998

SECTION

BRANCH COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE

	Filing Requirem	ent of Act 74, Mich. P.A.	1970 His or	MICHICHN
For corners in			Branch C Recorded	
BRANCH (County)	Located In:	Corner Code #	12-30-19	97 10:05:15
GILEAD TWP.	T <u>88R7W</u>	1-7		e Morrison-Mathews
Public Land Survey	TR		_	OF DEEDS
	ŢR		Liber U	0003 Page 0191
2. Property Controlling S	TR _ TR			
in Section S	TR		Register	of Deeds Stamp & File Number
3. Miscellaneous S	_ TR		1.09.0.0	
Property in Sec. S	_ TR			
4. Lot No, Recorded Pl 5. Private Claims			1 A B C	D R F G H I J K L M
		t	2 6 3	-5 - 4 - 3 - 2 - 1
			4 -7	8 9 10 11 12
, EDWARD W. REED	, in a field survey on	SEPTEMBER 23, 19 <u>97</u> do	5	
hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current				17 16 15 14 13
manual of survey instructions of the Management or by a decree of a Court of	United States Department	of the Interior, Bureau of Land	7	20 21 22 23 24
5 above were in conformance with the rul	les of the Michigan Board of	Land Surveyors or by a Decree of	9 19	-20 -21 -22 -23 -24
a Court of Law; established, re-establishe	d, monumented, recovered,	found as expressed below:	10 30	29 29 27 26 25 25 25 25 25 25 25 25 25 25 25 25 25
NOTE: Not more than 2 corners, all in the same town and range, may be recorded		11		
on this certificate.	•		12 31	_3'23'33'43'53'6
			ACCEPT	ED BY THE BRANCH COUNTY PEER GROUP AS THE OFFICIAL
A. Description of original monument and accessories and/or subsequent restoration: CORNER COMMON TO SECTIONS 14-15-22-23			CORNER CORNER OF 19	UNDER MICHIGAN PUBLIC ACT 345 90 AT A MEETING HELD ON
			12-	5. P. Ve d
1828: ROBERT CLARK JR, DEPT SURVEYOR - SET CORNER : M. KNOWLES, SURVEYOR - FOUND DEPOSIT OF EARTHEN AT DEPTH				E.R.REED
: M. KNOWLES, SURVEYO OF 2 FEET, FOUND NO S				2 ,,,,,
: H.K. GOTTSCHALK, SUR	•		FOUND SE	CTION"
B. Description of corner evidence to	found and/or method app	lied in restoring or reestablishi	ing comer:	
FOUND 1/3" X 8" IRON WITH FL	AGGING, NO STONE	LOCATED UNDER POINT	ſ	
SET 1/2" X 18" REBAR IRON WI	TH REMON CAP IN C	I-MONUMENT BOX 4" BE	LOW GRAVI	EL ROAD GRADE
C. Description of monument for	corner and accessories e	stablished to perpetuate locat	ing the position	n of the comer.
CONC. ANCHOR POST, EAST	10 21 TO TOD CENTE	.		W. FIEED
18" ASH, N55E 25.3' TO CENTE				LAND SURVEYOR
10" ASH, S19W 69.1' TO CENTI				NO.
ROUND WOOD CORNER POS' TEL. PED, N69W 54.3' TO FACI		DE ·		33985
·	•			CAND SO
AND IS ACCEPTED AS A CARE	FUL AND FAITHFUL	PERPETUATION OF THE	POSITION (OF THE ORIGINAL CORNER
	w/1.			
Signed by	Why		Date	SEPTEMBER 23 , 1997
EDWARD W. REED	/			·* ·*
Surveyor's Michigan License No.	33985			