

MAR I 0 1999

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Chippewa County Remonumentation Corners

Chippewa County	Located in:	Corner Code #
Public Land Survey	T44N T44N T44N T44N	R3W M-8 Corner R2W A-10 Same
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S T S T S T	R R R KEITH R WAIERS   R KEITH R  WAIERS
4. Lot No. , Record 5. Private Claims	ded Plat	PROFESSIONAL KE SURVEYOR NO. No. 3 3 1 4 2 PROFESSIONAL NO. OFFESSIONAL NO. OF

\$7.00 LAND CORNER \$2.00 MSSR 10:39:34 AM Receipt #14013 5 MAR 1999 RECEIVED FOR RECORD CHIPPENA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 10 PAGE 386

2 3

5

6

Register of Deeds Stamp & File Number

I, Keith R. Waters, in a field survey on October 16, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: A-8 1/4 Corner Common to Sec. 24, T44N, R2W & Sec. 19, T44N, R3W 1840 - Original corner established by William A. Burt.

Witnesses: Cedar 14, S80°W 22 links - Cedar 14, N55°W 15 links.

Found no evidence of subsequent restoration of this corner.

A-10 1/4 Corner Common to Sec. 25, T44N, R2W & Sec. 30, T44N, R3W 1840 - Original corner established by William A. Burt.

Witnesses: Fir 8, S21°W 20 links - Maple 6, N39°W 38 links.

Found no evidence of subsequent restoration of this corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being reestablished as part of the Chippewa County Remonumentation Program. Found no evidence of the corner. Reestablished corner by single proportionate measurement on the range line between recovered corners at A-4 and A-11. Distance between A-4 and A-11 is within 5 feet of GLO in 3½ miles.

This corner is being reestablished as part of the Chippewa County Remonumentation Program. Found no evidence of the corner. Reestablished corner by single proportionate measurement on the range line between recovered corners at A-4 and A-11. Distance between A-4 and A-11 is within 5 feet of GLO in 3½ miles.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

8-A

Placed a 3/4" x 24" rebar with a stamped aluminum Chippewa County Remonumentation cap at the corner location, which falls 3'± north of a ditch in a small ravine running into the Pine River. Witnesses:

Nail and plastic witness tag #33142 in side of blazed 24" Cedar, S60°E 31.89

Nail and plastic witness tag #33142 in side of blazed 8" Balsam Fir, N08°E 39.35'

Nail and plastic witness tag #33142 in side of blazed 8" Balsam Fir, N66°W 27.72'

Nail and plastic witness tag #33142 in side of blazed 24" White Pine, S46°W 26,79'


Placed a 3/4" x 24" rebar with a plastic Chippewa County Remonumentation cap at the corner location, which falls

approximately 3 feet east of the centerline of a north-south dirt road. Witnesses:

Nail and plastic witness tag #33142 in side of blazed 6" Spruce, N38°E 64.45'

Nail and plastic witness tag #33142 in side of blazed 6" Spruce, N50°E 52.76' Nail and plastic witness tag #33142 in side of blazed 11" Spruce, N80°E 30.38'

Nail and plastic witness tag #33142 in side of blazed 4" Spruce, S53°E 69.58'



Date 12-30-98

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

BOOK 10 PAGE 386

REVISED JAN., 1983 REVISED OCT., 1995