CLARE COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVEL EDIL #176-96 96 DEC 23 AM 11: 58

REGISTER OF DEEDS For corners in CLARE COUNTY DONNA M. CARR CLARE Located In: Corner Code # (County) 1. Public Land Survey 17N R 3W 2. Property Controlling in Section 3, Miscellaneous Property in Sec. Register of Deeds Stamp & File Number , Recorded Plat 5. Private Claims 2 3 in a field survey on November MARK R. ROBISON , 19 <u>96</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in 4 conformance with regulations and rules therefore as required in the current manual of survey instructions of the 5 United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan 6 Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 8 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 1850 BURT ON RIGHT BANK OF STREAM 12-18-87 LAPHAM-L.C.R.C.#551 COR FALLS ON RIGHT MARGIN OF STREAM 80.44 INT EAST BDY 38 LINKS S OF POST CAPPED IRON SET AT N-E & W FENCE CORNERS WIT.-LYNN 10 N88W 6 CORRECTED S89DEG. 14MIN.W 40.22 SET 1/4 SEC (NOTE: THIS CORNER SET IN ERROR) FIR 13 N32E 19 POST ON RIGHT MARGIN OF STREAM C.N.E. NOTES-COMM AT 23, 24, 25 & 26 SEC COR BTWN 24 & 25 N89DEG. 30MIN.E 00.65 OVER STREAM 1-4-17 C.S.R. C.S.E. WIT.-BASSWOOD 6 N36E 79 1/2 4.00 STREAM 70 C.S.E. BASSWOOD 6 S88DEG, 30MIN.W 13 31.00 STREAM 70 C.E. LINE IN STREAM L-9 TO M-9 40.20 (2653.20) **OFFSET 3.00 SOUTH** L-9 TO K-9 40.70 (2686.20) 40.00 OFFSET 3.00 NORTH & SET TEMP POST B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND 1987 C.I. NORTH OF RIVER. C.I. IS IN ERROR. SET NEW POSITION ON S.P.M. BETWEEN K-9 & M-9. CORNER FALLS ON SOUTH EDGE OF RIVER ALONG A NEARLY VERTICAL 6-8 FOOT HIGH BANK. SET IRON IN DEEP WATER AT RIGHT MARGIN OF RIVER. CORNER IS 2668.90 FEET E&W TO M-9 & K-9. C.S.R. OVERALL DIMENSION IS 5337.4 (MEAS 5337.8). 1917 NOTES PLACE CORNER AT 40.2 CH WEST OF M-9 WHICH IS 18.5 FEET EAST OF S.P.M., HOWEVER, THIS POSITION PLACES THE CORNER HIGHER UP ON THE BANK. I BELIEVE THE 1917 CORNER WAS SET AT RECORDED G.L.O. DISTANCE FROM THE TOWNSHIP LINE RATHER THAN AT S.P.M. THEREFORE, I ACCEPT THE S.P.M. LOCATION ON THE RIGHT MARGIN OF THE RIVER AND WITNESSED THAT POINT. APPROVED LAND CORNER P.A. 345 of 1990 Clare County SEE DOSSIER FOR DETAILED REPORT. Chairman_ Date 11-14-96 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: L-9: 1/4 CORNER COMMON TO SECTIONS 24 & 25 SET 3/4" X 60" PIPE IN DEEP WATER AT RIGHT MARGIN OF RIVER. ACCEPTED AS BEST AVAILABLE EVIDENCE OF THE POSITION OF THE CORNER. WITNESSES: N74E 87.11' N&T IN 5" ELM E OF MICHIGA N78E 1.94' N&T IN 8" IRONWOOD \$32E 4.53' N&T IN 8" IRONWOOD SOUTH 49.96' N&T IN 30" MAPLE MARK R. ROBISON **PROFESSIONAL** SURVEYOR No. 12.20-96

Surveyor's Michigan License No.

27458

POFESSION OFESSION OF