

3-71
NORTH $\frac{1}{4}$ COR.
SEC. 20

- S. $\frac{1}{4}$ COR. SEC. 17

BUGGED - NO LUCK
ROAD FILLED

STEADMAN WITNESSES

IRON PIN

^{FE} L IRON - N - 29.7

24" ELM - SW - 29.2 - 30.4

16" ELM - SE - 28.3 - 29.25