

(53)

3-31-71

N.E. COR - SEC. 33

COMMON TO SECS - 34, 27 & 29

REINFORCING)

FD - 1/2" PIN - FLUSH W/BIT

ON EXISTING CENTER OF ROAD

SOUTH - 28.57' T. POLE

N.55°W - 63.48' 15" C. ELM

N.20°W - 68.77' S.E. COR. FOND. HOUSE # 7011

5-18-71 - DUG LARGE HOLE - REMOVED  
PIN - DIDN'T FIND ANYTHING  
MORE - REPLACED 1/2" REINFORCING  
PIN AND SET MON. BOX.

Stephans

1969

P.P. 28183

SOUTH

16' oak 86126

NW

To Hickory 2155

NW

(54)