am a fee

COMMESSION

Filing Requirement of Act 74, Mich. P.A. 1970

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN
COUNTY OF CHARLEVOIX
RECEIVED FOR RECORD

. A #

For	corners	in	

	Charlevoix (County)	Located In:	Corner Code ##	1533 DEC 10 PM 4- 30
1.	Public Land Survey		F-1	REGISTER OF DEEDS
2.	Property Controlling			•
	in Section	S T R		
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4.	Lot No,	Recorded Plat		—— АВСОЕ <u>Е</u> G Н I J K L M
5.	Private Claims			2 6 5 4 3 2 - 1 -
l, .	Wayne E. Boss	_ , in a field survey onSept equirements of P.A. 74, Michigan P.A	ember 28 , 19 93	3 4 7 8 9 10 11 12 5 oned 6 18 17 16 15 14 13

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. John Mullett May 1840. Set 1/4 Sec. Post. 1. Beech 8. N.46°W.10. 2. Beech 6. N.43°E.32.

Restored by E.A. Robinson in May 1906. Set 1/4 Sec. Post from existing G.L.O. witnesses.

Marcus Schaaf set 2" pipe at location Carl Roser, PS, determined to be erroneous.

December 20, 1985 Carl Roser, PS, set DNR Mon. at E.A. Robinson location.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fd. DNR Mon. set by Carl Roser, PS, and whose method of restoration is recorded in Liber 2, Page 197, and reads as follows:

- F-1 -Fd. N 1/4 Cor. of Sec. 4, T32N-R4W (S 1/4 Cor. Sec. 33, T33N-R4W) per E.A. Robinson survey of North line of Sec. 4 dated May 1906; see Hudson (32-4) Book C-296, Pg.3. Restored cor. from E.A. Robinson N.B.T. (Hemlock Stp remains, S64°E, 22.4'). Fits E.A. Robinson tie 10.00 chains East to stream 20 Lks. wide. Any other latitude for 1/4 Cor. would not fit stream tie. Also fits E.A. Robinson distance 1/2 mile east (very close) to fd. SE Sec. 33. E.A. Robinson fd. both U.S. B.T.s at S 1/4 cor. of Sec. 4. Fd. Schaaf 2" pipe (dug pipe down flush w/ground), N61°18'E, 98.2'.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - F-1 Found DNR Mon. & Cedar Post per Liber 2, Page 197, Charlevolx County Records, Charlevolx County, Michigan, and is accepted as a careful and faithful reestablishment of the position of the original corner.

mondant and to seech		in iditili di 1000ta		
6" Maple	N45°E	31.6′	Fd. Blaze & Ta	g
10" Maple	S70°E	31.0'	Fd. Blaze & Ta	įg
12" Maple	S35°W	30.3'	Fd. Blaze & Ta	ıa
14" Twin Maple	N40°W	9.0′	Fd. Blaze & Ta	
				•

1/1/2	1/7		
Signed by	Ma San	Date	December 9, 1993
Surveyor's Michigan License No	20703		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197
· ,			REVISED MAY 14, 197