CONS. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as recorded by Marcus McNabb, county surveyor, in 1916. Found stakes in ground under road fill and hard maple NBT bearing South 36.10

Corner is buried in North shoulder of road.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED Silly LAND SURVEYOR
Billy D. Buckler