MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 38 N.R. 19W

					D _e lta_				COUNTY	
DESCRIPTION OF CORNER	Meander co:	mer for	r secti	ons	4-5 on	south	side of	Fayette	Harbor	
CORNER MONUMENT	3/8" X 24"	iron ba	ar							
DATE MONUMENT PLACED AND	WITNESSED	11-9-	61				<u>.</u>			
WITHESSES TO CORNER	•	911 W	Bi rc h	(B T)	NB9 ^O L	<u> </u>		İ		
N		12" W.	Birch	(BT)	N85°E	<u> </u>	23.51			
CIRCLE CORNER REGISTERED	AND									

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established at intersection of section line and lake shore. No evidence of original corner.

SURVEYOR'S SEAL

Signed Silly D. Buckler

Sienes DATE March 14, 1962

REGISTERED LAND SURVEYOR

Billy D. Buckler