Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 38-39 N.R. 19W

	Delta	COUNTY
DESCRIPTION OF CORNER Section	on corner for sections 3-4-33-34	
CORNER MONUMENT	be with 4" brass cap.	
DATE MONUMENT PLACED AND WITNESS	SED 9-15-61 with D. St. Ours	
WITHESSES TO CORNER	10" W. Ash (S3 NBT) S36°E 12.3'	
	ll" Hard Maple (S34 NBT) N41°E 7.3°	
38-19	9" Hard Maple (NBT) N59°W 3.0'	
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as set by unknown surveyor. Found a new B.T., a Butternut 14" bearing S36°E 14.4'. Found wood post and pile of stone in old fence corner.

SURVEYOR'S SEAL

SIGNED Sieger LAND SURVEYOR DATE March 14, 1962

Billy D. Buckler