SURVEY & REMONUMENTATION

AUG 2 0 1996

Approved By Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On June 27, 1996

LAND CORNER RECORDATION CERTIFICATE The Communication of the County of t

For corne	COMMISSIO	Filing Require	ment of Act 74, Mich. P.A	. 1970 Chairman
	DELTA (County)	Located In:	Corner Code ##	
1. Public	CLand Survey	T <u>38 R 23 W</u> T <u>R</u> R	B-3 (£ 5)	28 June 1996
		T' R		9:00 A.M. 8 Page /49
2. Prope	rty Controlling S_	T R		Walter C. Thomas may of Doesd's.
in Sec	ction S_	T R		Deita County, Michigen
3. Misce Prope		T R T R		Register of Deeds Stamp & File Number
4. Lot No	o , Record	ed Plat		A B C D E F G H I J K L M
o. Private	e Claims B-3 IN1/4 COR S7	'] B-5 (NI/4 COR S18]		2 6 5 4 3 - 2 1
	i i įmė, i dam bi	1 D 0 [, 1 00x 010]		3
ı V	P NIUTO in a	field august on Mi	ARCH	4 7 8 9 10 11 12
do hereby o	certify that under requireme	ents of P.A. 74, Michigan P.A. o	f 1970, the corner points mentione	ed
in lines 1 a current mar	ind 2 above were in confo nual of survey instructions	rmance with regulations and of the United States Departn	rules therefore as required in the nent of the Interior, Bureau of Lar	ne
Manageme	nt or by a decree of a Court	of Law and/or that the corner	points mentioned in lines 3, 4 and Land Surveyors or by a Decree o	
Court of L	.aw; established, re-estal	oles of the Michigan Board of blished, monumented, re-mo	numented, recovered, found	as 9
expressed		. all := the ===== t=		10 30 29 28 27 26 25
	n this certificate.	s, all in the same town and	range, may be recorded	12 31 32 33 34 35 36
A 0			or subsequent restoration:	13
N. N.	S.McNABB-1947-FD. IN PL DAVIS-1979-FOUND IN PLA	ACE WOOD POST SCRIBED "1/4 CE BOTH OF McNABB'S 1947 B	" AT JCT. OF FENCE LINES W.&	NKS) (CEDAR 12"-S68°W-33 LINKS) S. (CEDAR 14"-N32°W-28'(CEDAR 3"-S51°E-35.75) ENTED CORNER POSITION W/A 1° X 36° I.P. FROM WHIC ON PAGE 338
B-5 [N	1/4 COR S.18] WOOD POST RECORD EVIDENCE OF SUB	- A.MERRYWEATHER, D.S 1 SEQUENT CORNER RECOVERY OR	847 (HEMLOCK 24"-S43°W-48 LIN MONUMENTATION	(KS) (HEMLOCK 28"-N60°E-12 LINKS)
			plied in restoring or reestabli	· · · · · · · · · · · · · · · · · · ·
NO.	TED IN 1979 NOW DEAD WI	TH SCRIBING STILL VISIBLE.	MCNABB'S WOOD POST NOW BADLY	RIBED IN LIBER 2 OF LCR'S PAGE 338. W.BIRCH BT DETERIORATED. ON OF THE ORIGINAL CORNER POSITION.
AN: WI'	CIENT BLAZE LINES FOUND	RUNNING N-S & E-W FROM EX ITION FOR MANY YEARS. ACCE	ISTING CORNER MONUMENT. LOGGI	STILL PARTIALLY VISIBLE. NO EVIDENCE OF GLO "BT NG OPERATIONS IN THIS AREA APPEAR TO HAVE HONORES ING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION M. P.
C. Descri	ption of monument for o	corner and accessories es	tablished to perpetuate locati	DAVIS ing the position of the comeAND SURVEYOR
CEI	DAR 16" CEDAR 9"	BERNTSEN AINB30 ALUMN MON! CEDAR 8" MAPLE 6' S27'E S82'W	W/A 31/4" CAP STAMPED TO ID T SURVEY MONUMENT SIGN P SOUTH	
28	8.70' 29.80'	12.65' 26.10'	2.45' (TO FACE)	50 IA.O 3
MA! !N	PLACED EXISTING WOOD FO: PLE 10" HEMLOCK 10' 55°W N71°E 7.64' 26.80'	" MAPLE 10" HEMLO S48"E S5	MN MON W/A 3/1/4" CAP STAMPED OCK 10" SURVEY MONUMENT 9°W NORTH 78' 2.62' (TO	SIGN POST
			() =	·
NOTE: E	BEARINGS TO REFERENCE OF	BJECTS ARE MAGNETIC - DISTA	ANCES ARE TO A NAIL IN THE CE	NTER OF THE OBJECT UNLESS NOTED OTHERWISE
Signed by .	M.K. SAVIS		Date	9/96
Surveyor's	Michigan License No	16926	,,	