REMONUMENTATION APR 07 1995 COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved By Delta County Land Survey Remonumentation Peer Group Under Act 345 Of Of 1990 On Lept 29, 1994 The Selmaling wig Chairman

For	r corners in						A	_
	DELTA	Located In:	Corner Code ##		•			
	(County)							
1.	Public Land Survey	T <u>38 N</u> R <u>24 W</u> T R	C-5) k C-6	90°	T - 4 1994			
		T R T R		at ^{9:00} o'clock	AM in Liber	8 p	age_48	3
2.	Property Controlling in Section	S T R S T R	· · · · · · · · · · · · · · · · · · ·	Question County, M	2. Ilm			
3.	Miscellaneous	S T R		Register of De	eeds Stamn	& File	Numh	er.
	Property in Sec.	S T R						————
4.	Lot No,	, Recorded Plat		. A B	CDEF	GН	I J 1	KLI
5.	Private Claims	C-5 [NW COR S.17] C-6 [W1/4				Ť	Ħ	
		C-5 [NW COR S.17] C-6 [W1/4	COR S.17]	2 6	- 5 - 4 -	— 3 —	— <u>ż</u> —	 - -
				3			+	+
				4 - 7	\$_ \$		 1/1	 —12—
1, _		, in a field survey on		_ , 5	,	 	+	\bot
			A. of 1970, the corner points mention	0 1 10 4		 15	14—	13-
		•	and rules therefore as required in the partment of the Interior, Bureau of La					
		•	rner points mentioned in lines 3, 4 and	1 1 1				
			d of Land Surveyors or by a Decree o		20 21	1	1 23	
	•	, re-established, monumented, r	e-monumented, recovered, found	as	- -		1-1-	1
ext	pressed below:			10 30	29 28	27	26	25-
NC	TE: Not more than 4	corners, all in the same town	and range, may be recorded	11		 	++	+
	on this certificat	t e .		1231	3233	34—	35	36
				13		$\perp \perp$		
A.	C-5 [NW COR S.17] WOO 1884 RECORDS OF (OD POST - GEORGE ADAIR,D.S 1 C.E. BROTHERTON SHOW CORNER IN	and/or subsequent restoration: 852 - (HEMLOCK 30"-N54"E-47 LINK: PLACE-NO WIT'S NOTED OR DESCRIPT EE (CORNER FENCE POSTS-NELY-44.6'	ION OF EXISTING MO		Ī		

C-6 [W1/4 COR S.17] WOOD POST - GEORGE ADAIR, D.S. - 1852 (SUGAR 10"-N49"W-24 LINKS) (BEECH 14"-S19"E-10 LINKS) 1884 RECORDS OF C.E. BROTHERTON SHOW CORNER IN PLACE-NO WIT'S NOTED OR DESCRIPTION OF EXISTING MONUMENT GIVEN M.DAVIS-1974-SET TRACK SPIKE-ESTABLISHED CORNER POSITION FROM EXISTING OCCUPATION & IMPROVEMENTS (TELE POLE-N29°E-44.25') (POWER POLE-S70°W-31.6') NOTE: ACCESSORIES ESTABLISHED IN 1974 HAVE BEEN REMOVED OR DESTROYED

M.DAVIS-1974-SET TRACK SPIKE-ESTABLISHED CORNER POSITION FROM EXISTING OCCUPATION & IMPROVEMENTS (TELE POLE-N58'E-51.6')

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - C-5 INW COR S.17] FOUND TRACK SPIKE AS ESTABLISHED BY MYSELF IN 1974. THIS POSITION CORRESPONDS WITH EXISTING OCCUPATION & D.A.BROTHERTON'S 1907 SUBDIVISION OF SEC 17. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.

(POWER POLE-N45'W-41.5') NOTE: ACCESSORIES ESTABLISHED IN 1974 HAVE BEEN RENOVED OR DESTROYED

C-6 [W1/4 COR S.17] FOUND TRACK SPIKE AS ESTABLISHED BY MYSELF IN 1974. THIS POSITION CORRESPONDS WITH EXISTING OCCUPATION & D.A.BROTHERTON'S 1907 SUBDIVISION OF SEC 17. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.



REVISED JAN., 1983

				•	
C.	Description of monu	ment for corner and ac	cessories established to perp	petuate locating the position of the co	rner:
	C-5 SET INSIDE A MON	BOX A 5/8" X 18" REBAR	W/A 3-1/4" ALUMN CAF STAMPED	TO ID THE CORNER POSITION.	
	SE COR GARAGE	CORNER FENCE POST	SURVEY MONUMENT SIGN POST	POWER POLE	
	N81°W	N50°E	S43°E	S53°W	
	100,63	56.75' (TO FACE)	32.45' (TO FACE)	39.74' (TO FACE)	
,	C E COM THEIRD & MAN	DAY & E/O# V 10# DED#D	W/A 2_1/AP ATTIME CAD STRANDED	TO THE COUNTY POSITION	

SET INSIDE A MON BOX A 5/8 " X 18" KEBAR W/A J-1/4 ALUMN CAP STAMPED TO 10 THE CORNER POSITION. CORNER FENCE POST CHISELED "X" ON STORE SURVEY MONUMENT SIGN POST POWER POLE H42°E S45°E N43°W 857 W 55.02' (TO FACE) 25.79' (TO FACE) 42.40 34.16' (TO FACE)

OTE:	BEARINGS TO REFE	KFNCR	OBUECTS	AKL	MAGNETIC	-	DISTANCES. ARE	10	A MALI	 (THE	CENTER	Uŀ	THE	UDJECT	0117722	NUTLU	OTHERMISE
	· · · · · · · · · · · · · · · · · · ·	^															

Signed by _ Surveyor's Michigan License No. 16926 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975