SURVEY & REMONUMENTATION

Approved By Delta County Land Survey Remonumentation Peer Group Linder Act 345 Of

SEP 3 9 1999 Or 1990 On Mars 12, 199 A chine LAND CORNER RECORDATION CERTIFICATE SECTION wa Chairman Filing Requirement of Act 74, Mich. P.A. 1970 For corners in ADDITIONS BY DELTA Located In: Corner Code =## M. DAUIS 9/27 (County) 1. Public Land Survey M-2 &/M-3 MAY | 3 1994 Recorded 38N R 23W ,o'clock AM 9:00 397 R SAME **Property Controlling** R CORNERS c. 22 in Section S Т R Delta County, Michigan Miscellaneous S R Т Register of Deeds Stamp & File Number Property in Sec. s Т R _ , Recorded Plat 4. Lot No. Private Claims _ M-2 [E1/4 COR S.1] M-3 [NE COR S.12] M.P. DAVIS in a field survey on . APRIL do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 10 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 12 Description of original monument and accessories and/or subsequent restoration: M-2 [E1/4 COR S.1] JOHN BURT, D.S. - 1845 - ELM 3" CORNER TREE - (SUGAR 10"-N20"W-17 LINKS) (SUGAR 12"-N38"W-21 LINKS) D.A.BROTHERTON-1911-IDENTIFIED CORNER POSITION FROM ORIGINAL SUGAR BT-SET IRON STAKE (FENCE POST-S18°12'W.-19.6') ((FENCE POST-N28° 50'W-13.4') (FENCE POST-N49°47'E-63.5') (FENCE POST-N67°55'E-44.7') M.S.McNabb-1920-FOUND IRON BOLT IN PLACE (FENCE COR-NE-48.2') (ELM 4"-S63°E-30.6') (ELM 4"-S3°W-34.8') M.DAVIS-1970-REESTABLISHED CORNER POSITION BY RETRACEMENT OF M.S.McNABB'S 1920 SURVEY OF THE E-W 1/4 LINE OF S.6 T38M.R.23W SET 1" I.P. (MAPLE 24"-N53°E-87.27') (POWER POLE-S48°E-56.77') (POWER POLE-S75°W-21.35') M-3 [NE COR S.12] JOHN BURT, D.S. - 1845 - WOOD POST - (Y.BIRCH 8' NO B'RING OR DIST. GIVEN) (B.ASH 08" NO B'RING OR DIST. GIVEN) A.MERRYWEATHER, D.S. - 1847 - WOOD POST - (HEMLOCK 14"-N20°E-30 LINKS) (BIRCH 08"-S40°W-39 LINKS) from survey of T38N R23W 1940 RECORDS OF M.S. McNABE SHOWS CORNER IN PLACE-NO WIT'S NOTED OR DESCRIPTION OF EXISTING MONUMENT GIVEN Description of corner evidence found and/or method applied in restoring or reestablishing corner: MICH OF M-2 [E1/4 COR S.1] FOUND IP IN PLACE AS SET BY MYSELF IN 1970. ACCEPTED AS BEING A CAREFUL & FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER. M. P. DAVIS M-3 [NE COR S.12] FOUND IN PLACE & 20" M/L BELOW COUNTY ROAD SURFACE A 5/8" IRON PIN. EXISTING LAND SURVEYOR MONUMENT FITS OCCUPATION & ROAD IMPROVEMENTS AND IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE NO. OF THE POSITION OF THE ORIGINAL CORNER. 16926 RED LAND C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-2 REPLACED EXISTING IP W/A 5/8" X 18" REBAR W/A 3-1/4" ALUMN CAP STAMPED TO ID THE COR POSITION & RAISED TO RD SURFACE W/A MON BOX MAPLE 30* POWER POLE POWER POLE SURVEY MONUMENT SIGN POST N56'E S46°E S48°W **N46°W** 87.68 12.15' (TO FACE) 53.90' (TO FACE) 49.64' (TO FACE) M-3 SET OVER EXISTING MON & INSIDE A MON BOX A 5/8" X 18" REBAR W/A 3-1/4" ALUMN CAP STAMPED TO ID THE CORNER POSITION. COR FENCE POST POWER POLE C/L S. END CMP X-PIPE SURVEY MONUMENT SIGN POST N41°W N32°E S55°W S41°E 59.76' (TO FACE) 43.74' (TO FACE) 37 17 26.97' (TO FACE) NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC - DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT UNLESS NOTED OTHERWISE Milibraria _ Date _ 5/2/94

Surveyor's Michigan License No. 16926