SURVEY & REMONUMENTATION

DEC 07 1993

Approved By Delta County Land Survey Remonumentation Peer Group Under Act 345 Of P.A. Of 1990 On County 36, 199 3 Letting Chairman

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Fo	r corners in	rinng Requi	rement of Act 74, Mich. P.	4. 1970				
	DELTA	Loopted Inc	Corner Code ##			نے دو و مست		
	(County)	Located In:	Corner Code -77		DELTA CI	OUNTY		
1.	Public Land Survey	T <u>39 V</u> R23 W T R	(B-7) 6 C-1	LI	LIBER_ 1 FAGE 341			
_		T R T R			3 DEC -2			
2.	Property Controlling in Section	S T R S T R		T T	<i>Osti</i> s⊾ ∠. REGISTER 0		bo-	
3.	Miscellaneous Property in Sec.	S T R S T R		Register of D			nber	
	Lot No, I	Recorded Plat		A B	CDEF	3- H I J	K L M	
٥.		N TO SEC'S 18/19] C-1 [NW COR	SEC 5]	2 6 6	54-	32		
				4 7		_101	1——12—	
l, _		, in a field survey onMA						
		quirements of P.A. 74, Michigan P.A. conformance with regulations a			17—16	-15-1-1	4	
cur	rrent manual of survey instr	ructions of the United States Depa	artment of the Interior, Bureau of L	and 7				
		a Court of Law and/or that the corr ith the rules of the Michigan Board		of a	20 21	222	324	
Co	urt of Law; established,	re-established, monumented, re	-monumented, recovered, found	l as				
•	pressed below:			1030	29 28	—27 ——2	5——25—	
NO		corners, all in the same town a	and range, may be recorded	11				
	on this certificate	•		12 -31-	32 33	-343	53'6	
Α.	Description of original monument and accessories and/or subsequent restoration: B-7 [1/4 COR COMMON TO SEC'S 18/19] WOOD POST-1846-A.MERRYWEATHER D.S. (IRONWOOD 10"-N50°E-14 LINKS) (SUGAR MAPLE 20"-S23°W-16 LINKS M.S. MCNABB - 1914 - NO EVIDENCE OF ORIGINALS FOUND - ESTABLISHED BETWEEN CORNERS SET IRON STAKE - FENCE POST S76°30'W 44.8' C-1 [NW COR SEC 5] WOOD POST-1844-JOHN BURT D.S. (HEMLOCK 14"-N75°E-27 LINKS) (Y.BIRCH 16"-N49°W-24 LINKS)							
В.	A.MERRYWEATHER D.S 1846 - (HEMLOCK 14*-S24*E-17 LINKS) (HEMLOCK 7*-S20*W-4 LINKS) C.E. BROTHERTON - 1884 - ORIGINALS IN PLACE - NO NEW WIT'S NOTED M.S. McNABB - 1914 - ID FROM REMAINS OF ORIGINAL ET - BT STAKES NE & SW 33' M.S. McNABB - 1919 - SET IRON STAKE - BT STAKES IN PLACE M.DAVIS -1977 - L.C.R'S. IN LIBER 2 PAGE 147 Description of corner evidence found and/or method applied in restoring or reestablishing corner: B-7 [1/4 COR COMMON TO SEC'S 18/19] McNABB'S IRON STAKE APPARENTLY DESTROYED IN ROAD CONSTRUCTION - FOUND MCNABB'S 1918 C1/4 & CS1/1 OF SEC 18 & EXTENDED LINE S FROM C1/4 THRU CS1/16 & SET 1/4 COR ON THIS LINE A PROPORTIONATE DISTANCE S. OF CS1/16 ACCEPTED THIS POSITION AS A CAREFUL & FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER							
		UND MONUMENT AS SET BY MYSELF FUL & FAITHFUL PERPETUATION OF			E STATE OF THE STA	M. P. DAVIS AND SURV NO. 16926	EYOR	
C.	Description of monume	ent for corner and accessories	established to perpetuate loc	ating the position	of the corner	RED LAN		
		MON W/A 5/8" X 18" REBAR W/A A POWER POLE C.L. COUNTY \$82°E WES	ROAD 525	CE W/A MONUMENT BOX	Ι.			
	38.00'	\$82°E WES 23.83' 5.5						
		O ALUMN MONUMENT W/A 3-1/4" CA R FENCE POST SURVEY M S79°W	P STAMPED TO ID THE COR POSIT: CONUMENT SIGN POST S45°W	ION				
	46.03'		40' (TO FACE)					
	NOTE: BEARINGS TO REFE	RENCE OBJECTS ARE MAGNETIC & D	ISTANCES ARE TO A NAIL IN THE	CENTER OF THE OBJE	CT UNLESS NOT	ED OTHERW	ISE	
Sig	ned by	461/5	Date	1/15/23				
Sur	veyor's Michigan Licens	se No. <u>/69</u> 26						