SURVEY & PERON AND THE

FEB 1 8 1994

Surveyor's Michigan License No. 16926

Approved By Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On July 20, 199

	رة براه مهم ويوم على المراقبة الأنه المورسية المواجهة الأنه المورسية المواجهة	2. N. M. E. N 1 a. E 1943	ement of Act 74, Mich.	/	7
For	corners in DELTA			1	
	(County)	Located In:	Corner Code ##		
	D. Mile I and O. annu	T 40 M D 30 M	E. S. C. S.		
1.	Public Land Survey	T <u>40 N</u> R <u>22 W</u> T R	<u>1-3 #(6-3)</u>	Recorded January 21, 1994	_
		T 🕏		9:00 o'clock m. in Liber Pa	350
_	December On the Utan	T R S T R		or o'clock in Liber Pa	
2.	Property Controlling in Section	SR		Delta County, Michigan	of Deeds.
3. Miscellaneous S T R				Register of Deeds Stamp & File No	
	Property in Sec.	S			
4.	Lot No , R	ecorded Plat		A B C D E F G H I	
	Private Claims			2	ŤÌŤ
	[F-5] N1/4 COR SEC 16	[G-5] NW COR OF SEC 15		3 5 5 4 3 3	-21-
				4 7 8 9 10	-1112-
١,	M.P. DAVIS	in a field survey onN	VEMBER , 19 , 19	93 , 5	11
do io l	hereby certify that under rec	quirements of P.A. 74, Michigan P.A. n conformance with regulations a	. of 1970, the corner points me	entioned 6 18 17 16 15	-1413-
cur	rent manual of survey instru	ctions of the United States Depa	rtment of the Interior, Bureau	of Land 7	
		a Court of Law and/or that the corn th the rules of the Michigan Board			-23 24
		re-established, monumented, re-		ound as	-
	pressed below:			10 30 29 28 27	-26 -25
NO	TE: Not more than 4 c on this certificate.	orners, all in the same town a	ind range, may be record	ed 11 12 31 32 33 34	
	on this certificate.			13 32 33 34	35 36
	M.S. McNABB - 19 G-5 [NW COR SEC 15] F.J. MERRIAM - 18	144 - FOUND IRON BOLT IN PLACE 100D POST - A. MERRYWEATHER, D 195 - SET LENGTH OF RAIL - PLA	- NO NEW WIT'S. NOTED S 1846 -(CEDAR 8"-S18 OF FURNACE ADD TO GLADS	-S20°W-4 LINKS) (TAMERAC 12°-N47°E-15 LINKS PE-7 LINKS) (CEDAR 8°-N15°W-13 LINKS) PONE -REC'D LIBER "B" OF PLATS PAGE 8 - NO E REMOVED THE LENGTH OF RAI AS IT HINDERED	VIT'S NOTE
В.	F-5 [N1/4 COR SEC 16 THE EXISTING ROAD	evidence found and/or method FOUND, TEIS DATE, THE REMAIN SURFACE - ID COR POSITION BY MON AS A CAREFUL & FAITHFUL	S OF A WOOD POST & AN IRO MEASUREMENTS E & W TO AD	N PIN 24" BELOW JOINING CORNERS SITION OF THE M. P.	A C PZ
	"SOO LINE" RR R/	RESTORED CORNER POSITION FROM W AS CONTAINED IN THE PLAT OF GAITHFUL REESTABLISHMENT OF TH	SAID FURNACE ADD. ACCEPTE	B THIS POSITION	100
C.		NG MON. & 4" BELOW ROAD SURFACE CEDAR 13" FOWER POLE N35°E S65°E	CE A 5/8" X 18" REBAR W/A SPRUCE 9" SURVEY MONUM S32"W	e locating the position of the corner: 3-1/4* CAP STAMPED TO ID THE COR POSITION LENT SIGN POST NORTH 1. (TO FACE)	
			BAR W/A 3-1/4" ALUMN CAP S 3" NLY EDGE CONC WLK S36°W	TAMPED TO ID THE CORNER POSITION	
	NOTE: BEARINGS TO RE	SERENCE OBJECTS ARE MAGNETIC	G DISTANCES ARE TO A NAIL	IN THE CENTER OF THE OBJECT UNLESS OTHERWIS	SE NOTED
٥.	10.01	lesi Mi		11/15/23	
519	gned by/////	77073	Date	11/12/23	

LISER