OCT 2 6 1995

COMMISSION

Approved By Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of
A. Of 1990 On Jeps 22, 1995

LAND CORNER RECORDATION CERTIFICATE

PA 01 1990 On Sept 22, 1993

_		Filing Re	equirement of Act 74, Mich.	P.A. 1970 <i>CE</i>	tary Chairi	nan	
For	Corners in DELTA (County)	Located In:	Corner Code ##		•	•	
1.	Public Land Survey	T <u>41 N</u> R <u>1</u> T R	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Recorded			
		T R		at 9:00 clock	Min Liber_U	9 Page 160	
2.	Property Controlling in Section	T R S T R S T R		Delta County, Mic	higen	_Reg. of Deeds.	
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number			
				A B	C D E F	G H I J K L M	
	L-13 [S1/	4 COR SEC 36] M-9 [NE COR	SEC 25-SAME AS A-9 T41N R18W]	3	3 - 1 -	3 - 2	
		•	SEPTEMBER , 19 9	35 5	 	10 11 12	
in I cur Ma abo Cor exp	hereby certify that under re ines 1 and 2 above were trent manual of survey inst nagement or by a decree of ove were in conformance w urt of Law; established, pressed below:	equirements of P.A. 74, Michig in conformance with regulati ructions of the United States is a Court of Law and/or that the ith the rules of the Michigan E re-established, monumente	an P.A. of 1970, the corner points menons and rules therefore as required Department of the Interior, Bureau cacorner points mentioned in lines 3, 4 Board of Land Surveyors or by a Decrid, re-monumented, recovered, fou	1 in the 1 in the 2 in the 3 in the 3 in the 3 in the 4 and 5 in the 4 and 5 in the	20-21-29-28		
NO	TE: Not more than 4 on this certificate		own and range, may be recorded	d 11 12 31 13	32 -33	34-35-36-	
A.	Description of original	monument and accessori	es and/or subsequent restoratio				
	M.S.McNabb-1920-RESTORED CORNER POSITION 331' WEST OF NE COR OF SECTION 3 T40N R19W DURING HIS SECTION SUBDIVISION OF SAID SEC NO WIT'S NOTED OR DESCRIPTION OF MONUMENT GIVEN IN MCNABB'S RECORDS. M-9 [NE COR SEC. 25] A.MERRYWEATHER, D.S 1848 - WOOD POST (HEMLOCK 08"-N45°E-09 LINKS) (CEDAR 14"-S56°E-12 LINKS) JOHN BURT, D.S1845-WOOD POST (Y.BIRCH-S80°W-25 LINKS) (CEDAR 14"-N18°W-22 LINKS) JOSEPH E. GINGRASS - 1906 - ID "FROM ORIGINALS" NO NEW WIT'S NOTED						
В.	Description of corner evidence found and/or method applied in restoring or reestablishing corner: L-13 [S1/4 COR SEC 36] NO EVIDENCE OF McNABB'S CORNER FOUND. REESTABLISHED CORNER POSITION ON 4TH CORRECTION LINE & 331' WEST OF NE COR SEC 3 T40N R19N. CORNER POSITION MATCHES WELL WITH COUNTY ROAD CONSTRUCTION TO THE NORTH. ACCEPTED THIS POSITION AS BEING A CAREFUL & FAITHFULL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER. M. P. DAVIS						
	AS THIS AREA HAS BE BY DISTANCE DISTAN	GEN GREATLY DISTURBED IN L	ON MENTIONED IN THE 1906 RECORDS OGGING OPERATIONS. RESTORED CORN E N1/4 COR & NORTH FROM THE E1/4 INGRASS'S 1906 SURVEY.	ER POSITION BY	LAND	NO. 16926 SHE	
C.	Description of monum L-13 SET, 6* BELOW ROAL ELM 6" ASH 5" S54°N N62°W 40.34' 57.20'	O SURFACE, A 5/8" X 18" RE COR FENCE POST N33°E	pries established to perpetuate I BAR W/A 3 ^{1/4} " ALUMN CAP STAMPED SURVEY MONUMENT SIGN POST SOUTH 15.04' (TO FACE)	locating the position 70 ID THE CORNER POS	of the corner		
	M-9 SET A BERNTSEN ALM MONUMENT SIGN H EAST 2.41' (TO FAC	POST MAPLE 6" CI N13°E	74° ALUMN CAP STAMPED TO ID THE EDAR 4" NOTE: AREA HAS BEE N52°W THE SE & SW 9 54.11'	N CLEAR CUT IN			
NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC-DISTANCES ARE TO A NAIL W/A DELTA COUNTY REFERENCE TAG, UNLESS OTHERWISE NOTED.							
Sia	ned by	ani .	Date	9/27/95	·		
Sur	veyor's Michigan Licen	se No. <u>16<i>926</i> </u>			N STATE BOARD OF LA	AND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983	