

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T...43 NR. 22W. . . .

----- Delta ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 14, 15, 22, 23 . . .

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap . . . . .

WITNESSES TO CORNER 10" Cedar ----- Marked "N 58° W S 15 NBT" ----- 98 links . . . . .

10" Soft Maple ----- Marked "N 33° E S 14 NBT" ----- 59 links . . . . .

Power Pole ----- S 26° E ----- 38 links . . . . .

-----  
DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner as set by unknown Surveyor.

Cedar Post in place.

Found evidence of Tamarack Stp. bottom at Corner as per:  
Gort Field Notes

Corner lies at Intersection of County Roads South and East

Distance checks with Section Corner one mile North.

Corner placed and witnessed October 31, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 11/21/56  
REGISTERED LAND SURVEYOR