MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_41 NR_28 W. T 40 NR 28 W

			DickinsonCOUNTY
DESCRIPTION	OF	CORNER	Section C rmer common to Sections 33,34,6
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with 4" Bress cap
WIT TNESSES	то	CORNER	9" Temarack - H 38 E - 193 Links
			9* Tamarask - N S W - 175 Links
		•	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Two original B.T.'s still in place, in poor condition. Corner was placed and witnessed July 21, 1954.

SURVEYORS SEAL

SIGNED LAND SURVEYOR 2/11/55