MAR 0 3 1998

-476-	FC	ALC: N		N.
(C)			1 1	N
_		π O 1		

· LAND CORNER RECORDATION CERTIFICATE

RECORDED

Filina	Requirement	of A	ct 74	Mich.	P.A.	1970

For corners in	Filing Requireme	ent of Act 74, Mich. P.A. 1970) 1797 DEC 10 PM 3: 57
Dickinson	Located in:	Corner Code #	
Norway Twp.			REGISTER OF DEFENS
1. Public Land Survey	T <u>40N</u> R <u>29W</u> T R T R T R	E-1 E-2	FON HE LEST THEOLOGIC
Property Controlling in Section Miscellaneous	ST R ST R ST R ST R		egister of Deeds Stamp & File Number
Property in Section	3 n		
	ecorded Plat		- ABCDÆFGHIJKLI
5. Private Claims			
. Dohows V Dowleino		Sont 22 07	4 7 8 9 10 10 11 12 12
do hereby certify that under rec	, in a field survey on uirements of P.A. 74, Michigan P.A. of	F1970, the comer points mentioned	5
	onformance with regulations and rules		6 18 17 16 15 14 13
manual of survey instructions	of the United States Department	of the interior, Bureau of Land	7
	a Court of Law and/or that the corner		8 19 20 21 22 23 24
	with the rules of the Michigan Board blished, re-established, monumented,		9 -1-4
as expressed below:	onoriod, re-octabilotica, riprioriotica,	To monamentou, rocovereu, round	10 30 29 28 27 26 25
NOTE: Not more than 4 co.	ners, all in the same town and rar	nge may be recorded	11
on this certificate.	ners, an pricing same town and tar	igo, may oo roco, coc	12 31 32 33 34 35 36-
			13
A. Description of original	monument and accessories and/	or subsequent restoration:	
E-1 Northeast	Corner, Section 5	E-2 ½ Corner	to Sections 5/4
Post by J	.H. Mullett, D.S. 1848	Post by	J.H. Mullett, D.S. 1849
	Bearing Trees	Original	. Bearing Trees
Hemlock 24	4" S55°W 25 Lks.	W.Pine 1	4" N12°W 05 Lks.
Hemlock 10)" S57°E 40 Lks.	(8" NA6 E THE DICKINSON COUNTY COLPTED BY THE DICKINSON COUNTY SURVEY PEER GROUP AS THE OFFICIAL COHNER UNDER MICHIGAN PUBLIC ACT

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:

No Evidence of Original Corner or Accessories Found. Found 1" Iron Pipe with 4" D.N.R. Brass Cap set by D.C. DeLaMater, RLS in 1955. No Witnesses available at that time.

(01d Report #61)

Found Remains of Orginal Pine B.T. Stump N12°W 3.3'. Found 1" Iron Pipe with 4" D.N.R. Brass Cap Set by D.C. DeLaMater, RLS in 1955. 1955 Bearing Trees: W. Ash 9" N13°E 31 Lks. Y.Birch 24" N60°W 25 Lks. (01d Report #53)

345 OF 1990 AT A MEETING HELD ON

COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-2

E-1Found and Accepted above described Monument. New Witnesses: Maple 8" S21°W (M.B.) 24.49' Nail/Tag Maple 7" S66°E (M.B.) 16.09' Nail/Tag Maple 6" N28°E (M.B.) 34.98' Nail/Tag Maple 3" N79°W (M.B.) 17.70' Nail/Tag Carsonite Marker South 1.1'

Found and Accepted above Described Monument. New Witnesses:

Maple 3" N46°E (M.B.) 8.12'Nail/Tag Maple 3" S25°E (M.B.) 46.86'Nail/Tag Maple 8" N83°W (M.B.) 22.13'Nai1/Tag Ironwood 3" S12°W (M.B.) 17.43'Nail/Tag Carsonite Marker North 1.0

12027

Surveyor's Michigan License No.

Nov. 19, 1997 Date

FORM APPROVED BY MICHIGAN STATE BOARD O

