JAN 0 4 2001

SE	10	N
· • • •	 3 % /	11.4

RECORDE)
---------	---

•		LAND CORNER	RECORDATION C	ERTIFICATE		the same beautiful
For core	ners in	Filing Requirem	ent of Act 74, Micl	n. P.A. 1970	1797 DEC	10 PM 3: 57
_Dicl	cinson (County)	Located In:	Corner Code #	1		
Norv	ay Twp.				REDIGER	(2) prop
1. Pub	lic Land Survey	T 40N R 29W T R T R T R	(I-1) K-1	- - -	HICKLING HELVINGS	A BE DEEDS SECONTRY
in S	perty Controlling ection	S T R S T R		- - -		
	cellaneous perty in Section	S T R S T R		Register of	f Deeds Stamp	& File Number
4. Lot	No, Re ate Claims	corded Plat			BCDEF	G H J J K L
0. 1110				2	 	3
				3		+
ı Robe	rt F Parkine:	n a field survey on	Sent 23 40	97	7	10-11-12-
do hereb	y certify that under requi	irements of P.A. 74, Michigan P.A. o	f 1970, the comer points	mentioned	181716-	
in lines 1 manual	and 2 above were in cor of survey instructions	nformance with regulations and rules of the United States Department	therefore as required in	the current		15 14 13
Manager	nent or by a decree of a	Court of Law and/or that the corne	r points mentioned in lin	es 3, 4 and 8—	192021-	22 23 24-
b above Decree o	were in conformance w f a Court of Law; establi	ith the rules of the Michigan Board ished, re-established, monumented,	I of Professional Survey , re-monumented, recov	ors or by a 9ered, found		
as expres	ssed below:			10 3	302928-	27 26 25
	Not more than 4 corn on this certificate.	ers, all in the same town and rai	nge, may be recorded	1	31 - 32 - 33-	34 35 36
				13		
		onument and accessories and/	•			
I-1	Post by J.H. Original Bea Hemlock 6"	orner, Section 3 Mullett, D.S. 1848 aring Trees S23°E 15 Lks. S19°W 07 Lks.	K-1	Birch 8" S25' ALOUS SUHVI CORN 845 C	ullett, D.S ng Trees °E 25 Lks. °W 39 Lks. FTLD BY THE D LY PEER GROU	5. 1848
B. Des	cription of corner evi	dence found and/or method ap	plied in restoring or	reestablishing corner:	COUNT	Y REPRESENTATIVE
I-1	No Evidence or Assessors Found 1" Iro Brass Cap Se in 1956. 1956 Bearing Balsam 12"	of Original Corner ies Found. on Pipe with 4" D.N.R. et by B.D. Buckler, RL g Trees: S72°W 40 Lks. S31°E 65 Lks.	K-1	No Evidence of or Assessories Found 1" Iron 1 Brass Cap Set 1 in 1955. 1955 Bearing To Hemlock 16" Se Hemlock 18" Si (Old Report #6)	Original (Found. Pipe with 4 by D.C. Del rees: 46°E 105 I 16°W 148 I	Corner 4" D.N.R. LaMater, RLS
C. Des	cription of monument	t for corner and accessories es	tablished to perpetua	ate locating the position	on of the come	ır:
I-1	Pipe Monumer New Witnesse Maple 5" NI Maple 7" No Maple 6" S2 Maple 3" S8		1/Tag 1/Tag 1/Tag		5°E (M.B.) 9°W (M.B.) 3°W (M.B.) 6°E (M.B.) er North (18.75'Nail/Ta 18.92'Nail/Ta 28.48'Nail/Ta 69.9' Nail/Ta
			*	Existing 1955	B. T.	OF MICHORA
Signed b	y / Com	#OPER	D a	te Nov. 19, 199)7 🖹★・	ROBERT **

12027

Surveyor's Michigan License No._