## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 41 NR 28 W

			Interpretation COU	INTY
DESCRIPTION	OF	CORNER	Section Corner common to Sections 28,29,32,33	_
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with 4" Bress wap	
WIT TNESSES	то	CORNER	12" Tamarack - N 6 E - 14 Links	-
			5" Tamarack - 8 82 W - 49 Links	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial reservey of this Township. One original B.T. still in place, down, in fair condition.

Corner was placed and witnessed July 20, 1954.

SURVEYOR'S SEAL

SIGNED LAND SURVEYOR DATE 2/11/55