CONS. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 43\_44 N.R. 27W

	Dictinson	COUNTY
DESCRIPTION OF CORNER Section Corner common to Secs	. 1-2-35-36	
CORNER MONUMENT _ 1" Pipe with 4" Aluminum Cap		
DATE MONUMENT PLACED AND WITHESSED 1/31/64 with R. Sm	ith, Marquette	
WITHESSES TO CORNER6" B. Spruce (S 2 NBT) 540	V 14 Lks	
5" Tamarack (S1 IBT) S70°E	32½ Iks.	
43-27 AND		

## DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at old Wood Posts set by unknown Surteyor. Found Cedar Stump bottom bearing S61°E 17 Links and a down Cedar bearing S41°W 20 Links for two probable Original B.T.s.

SURVEYOR'S SEAL

Billy Q. Buckler

MFD BILLY D. BUCKTER

\_\_\_\_

DATE <u>8/4/1964</u>