

JAN 9 1956

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 NR. 30 W.

Dickinson

..... COUNTY

DESCRIPTION OF CORNER Section corner common to sections 29,30,31 and 32

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 7" tamarack N 33 W 25 links

8" tamarack S 44 E 38 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from original tamarack bearing tree in good condition.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 1 December 1955.

SURVEYORS SEAL

Henry S. Petersen
SIGNED Henry S. Petersen
REGISTERED LAND SURVEYOR

DATE 12/3/55