EATON COUNTY REMONUMENTATION

DEC 1 2 1997 COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

REVISED MAY 14, 1975 REVISED JANUARY, 1983 REVISED OCTOBER 1995

e week		Ü	•		97 OCT 14 PM 12: 46
			Camar Codo #	1	•
For Corners in	,	Located In:	Corner Code #	1	I IND'A M TWITCHELL
<u>EATON</u> (county)	,		, t+	İ	LINDA M. TWITCHELL REGISTER OF DEEDS
(vount))			ž	1	EATON COUNTY, MICH.
1. Public Land Survey		T_1N_R_6W	A-6		A NAME OF THE PROPERTY OF THE
WEST 1/4 CORNER		TR		1	
SECTION 18	מו	TR T R		1	11
BELLEVUE TOWNSH ON RANGE LINE	112	I IN			· Liber 3 pg 818
2. Property Controlling	s	T R		Ī	1 2
in Section	s	T R		<u> </u>	Register of Deeds Stamp & File Number
•		<u>_</u>		•	
3. Miscellaneous	s	T R			
Property in Sec.	S	I R		•	
4 Lot No. Rec	orded Pla	at		<u></u>	
4. Lot No, Rec 5. Private Claims	oldod i ic	N. T. Carlotte		· ·	A B C D E F G H I J K L M
					6 5 4 3 2 1
I, Brian Reynolds, in a field s	survey on 8 .	JULY,1997 do hereby o	ertify that under requiren	nents 3	7 8 9 10 11 12
of P.A. 74, Michigan P.A. of 19	970, the con	mer points mentioned in	lines 1 and 2 above were	ein 4	7 8 9 10 11 12
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by					
instructions of the United State a decree of a Court of Law and	es Departme	ent of the Interior, Burea	tion lines 3 4 and 5 abo	ve 7	
were in conformance with the	nules of the	Michigan Board of Land	Surveyors or by a Decre	e 8	19 20 21 22 23 24
of a Court of Law; established	, re-establis	hed, monumented, re-m	onumented, recovered, t	ound 9	
as expressed below.				10	
				11	31 32 33 34 35 36
NOTE: Not more than 2 corr	ners, all in t	the same town and rai	nge, may be recorded	13	
on this certificate. A. Description of original	monumen	t and accessories a	nd/or subsequent res	toration:	
NOTE: CLOSING 1/4	CORNER	WAS NOT SET	BY GENERAL LAN	ID OFFICE S	JRVEY. ITEMS 1 AND 2 BELOW REFER $^{rac{1}{4}}$
	~		INICO .	, ,	the state of the s
1. GENERAL LAND O	FFICE: J	JOHN MULLETT,	D.S., (NO MONTH	I)1825 (I 1N, F	R6W, P. 494), "40.00 SET 1/4 SEC POST"
2. GENERAL LAND OFFICE SURVEY: JOHN MULLETT, D.S., DEC. 1825 (T1N, R7W, P. 5) "40.00 SET POST 1/4 SECTION CORNER" BEECH 6 N40W 06 Do. 6 S37 1/2W 22					
TANGE LINE DETAILED TAN DE 9 7W WAS ADDARENT! Y RIIN ON TWO SEPARATE OCCASIONS ***					
3. NO MENTION OF THIS CORNER COULD BE FOUND IN THE RECORDS OF THE COUNTY SURVEYOR OF BARRY					
AD EATAN A	NINTIEC	•			·
*** NO OTHE	RHISTO	ORICAL INFORMA	ATION, PUBLIC O	R PRIVATE, A	VAILABLE FOR THIS CORNER ***
	. Jahan sa fa	und and/ar mathod	annlied in restoring (or reestablishing	corner:
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND NO MAGNETIC EVIDENCE OF CORNER MONUMENTATION AT EITHER STANDARD CORNER OR CLOSING CORNER.					
THE STEPS OF STATE OF C	TATION	40 INICH HIDINIC CT	ΓΛΝΙΝΑΡΙΝ CORNE	RS FXCAVAI	HON AT APPAKENT STANDARD CORNER
DOCITION BEVEN ED	TRACES	OF OLD MONUME	INTATION IN THE I	-UKM UF A SI	CALLERING OF COAL DELIVERY THE OPTI
COADE AND THE COA	VEL EY	CAVATION AT CL	OSING CORNER R	EVEALED NO	EAIDENCE OF LKEA1002
MONUMENTATION ACCEPTED FOLIND COAL AS BEST AVAILABLE EVIDENCE OF STANDARD CORNER POSITION.					
ACCEPTED MID-POINT BETWEEN A-5 AND A-7 ON RANGE LINE AS PROPER POSITION OF CLOSING CORNER. SET STANDARD EATON COUNTY REMONUMENTATION MONUMENT AT MID POINT (A-5 TO A-7) ON RANGE LINE.					
C. Description of monume	ent for cor	ner and accessories	established to perpe	tuate locating tl	ne position of the corner:
CET STANDARD FAT	ON COUI	NTY REMONUME	NTATION MONUS	//ENI(3/4 A	90 IMOIN MILLILE POLIO ANT.
SET 20d NAIL W/REMON TAG IN THE TOP CENTER OF A WOOD FENCE POST S20°W 88.73' SET 20d NAIL W/REMON TAG IN THE TOP CENTER OF A WOOD CORNER POST S35°W 51.96'					
SET 20d NAIL W/REM	ON TAG	IN THE TOP CEN	TER OF A WOOL	SORVER PU	A'
SET 20d NAIL W/REMON TAG IN THE WEST SIDE OF A 26" OAK S08°E 188.34' SET 1/2" x 18" IRON W/TRAVERSE POINT CAP N54°E 43.21'					
SET 1/2" x 18" IRON V	W/TRAVE	RSF POINT CAP	S43°E 60.02'		La Oliveria
M-6, T1N, R7W, ASSYI	RIA TOW	INSHIP, LIES SO	JTH 42.40'		BRIAN
1/2" IRON W/TRAVERSE POINT CAP (BL1-52-149-TP) LIES S32°W 21.23" REYNOLDS \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					
2'+/- WEST OF NORTH-SOUTH GRAVEL CENTERLINE (CURTIS ROAD) LAND SURVEYOR					
12'+/- NORTH OF GRAVEL CENTERLINE EAST (LINK HIGHWAY) 42'+/- NORTH OF FENCE LINE WEST NO.					
42'+/- NORTH OF FEN	CE LINE	AAE9 I			31602
			P.A. 345 EATC	NI COLINITY	The second secon
		A	P.A. 345 EATC PEER APPROVED	7/11/100	M (AND S
		\/\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	PEER APPROVED	1100111	The state of the s
	1	1_1			
(<~	-11			Data X	-15-97
Signed by		<u> </u>		Date	
Surveyor's Michigan Lic	ense No	31602		FORM APPROV	ED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197