## SURVEY & REMONUMENTATION

JUN 2 8 1994

LIBER 3 PAGE

94 MAR 25

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE

| Filing Require  | ement of Act 74, Mich. P.A.  | 1970   |
|---|--|--|
|   |  | REGISTER OF DEEDS<br>EATON COUNTY, MICH.   |
| Located In:   | Corner Code ##   | EATON COUNTY, PRICE.   |
| T R<br>T R<br>T R   | M-8  |  |
| T R<br>T R<br>T R   |  | Register of Deeds Stamp & File Number  |
| ed Plat   |  | A B C D E F G H I J K L I  |
| nts of P.A. 74, Michigan P.A. rmance with regulations are of the United States Depart of Law and/or that the cornules of the Michigan Board slished, monumented, respectively, all in the same town a | of 1970, the corner points mentione and rules therefore as required in the triment of the Interior, Bureau of Laner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of monumented, recovered, found a and range, may be recorded | te d 7   |
| s "Set 1/4 pos<br>evember 1825.<br>mation found<br>70 recorded Li<br>LCRC "Set 1/2<br>and tag SW si<br>East, 22.37'; SEE BACK OF  | in county records. ber 1, Page 199, 1 bar on Town line de 8" maple SE 38.2 Set nail and tag No   | 12/14/1972 by R. Lester LS<br>on old fence line West."<br>23'; Set nail and tag North<br>orth side 16" walnut, West,   |
|   | T  | T R M M-8  T R M M M M-8  T R M M M M M M M M M M M M M M M M M M |

Investigation at this site revealed a 1/2" bar in monument box located 5' East of centerline of Royston Road. I found this corner to be the same as recorded in Liber 1, Page 199 and also in Liber 2, Page 776. I accept bits the East 1/4 corner (M-8) of Section 24. OF MICHIGAN

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

East 1/4 corner Section 24, T2N, R4W. Fd. 1/2" bar in monument box. Set galvanized nail and 1 1/4" brass tag stamped "LS 18998" North side 10" ash, 296° az., 44.15' Set galvanized nail and 1 1/4" brass tag stamped "LS 18998" West side 18" ash,

159° az., 72.00'

1/2" bar in monument box, 184° az., 60.55'

Northwest corner of pole barn, 171° az., 322.90'

Found nail and tag #11370 in South side 4" ash, 279° az., 50.40'

Found nail and tag #11370 in South side 12" ash, 148° az., 63.61'

| Signed by Ramio M. Recto              | March 21, 1994   |
|---------------------------------------|--|
| Surveyor's Michigan License No. 18998 | FORM APPROVED BY MICHIDAN STATE BOARD OF LAND SURVEYORS, JAN. 28 |
| Surveyor S Michigan License No.       | FORM APPROVED BY MICHIGAN SINIE BURBO OF CARD SONTETONS, SAN. CO |

RONNIE M. LESTER PROFESSIONAL SURVEYOR No. 18998 OFESSION

## SECTION "A" OF M-8, T2N, R4W, continued

LCRC P.A. 74 of 1970 recorded 10/15/1981 by R. Steadman LS #11370 dated 10/08/1973.

He states "Dug hole in Royston Road and found railroad spike at location given by witnesses in Liber 1, Page 199. Continued digging but found no additional evidence"

Witnesses: 1/2" bar and cap 60.60 South; Nail and tag in 5" walnut S36°E, 63.40'; Nail and tag in 3" ash, N84°W 50.36'; Nail and tag SW side 8 maple SE 138.23'; Nail and tag in North side 14" boxelder, East, 22.37'; Nail and tag in North side 16" walnut, West, 36.88'

Various surveys per P.A. 132 of 1970 recorded.

Liber 2, Page 725, July 20, 1978, L. Hendryx LS #3276. Indicates corner but no witnesses given.

Liber 2, Page 726, July 20, 1978, L. Hendryx LS #3276. Indicates corner but no witnesses given.

Liber 2, Page 727, July 20, 1978, L. Hendryx LS #3276. Indicates corner but no witnesses given.

Liber 3, Page 87, September 25, 1979; R. Lester LS #18998. Witnesses: Nail and tag in 5" walnut, SE, 63.40'; Nail and tag in 3" ash, WNW. 50.36'; 1/2" rod and cap South 60.03.'