## SURVEY & REMONUMENTATION

APR 27 1995

1981 J. Green

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN EMMET COUNTY RECORDED

1994 JUN -2 PM 2:51

Fo	r corners in EMMET		of Act 74, Mich. P.A. 1970	Glema a. Signo REGISTER OF DEEDS
	(County)		orner Code ##	Duna a. Alpe
		Bear Creek Township		REGISTER OF CEEPS
1.	Public Land Survey	T 35N R 5W H-1	3	or DEEDS
	ECRP #48	T R T R T R		LIBER A
2.	Property Controlling			
	in Section	S T R		
3.	Miscellaneous	S T R		sister of Doods Stown & File Nambar
	Property in Sec.	S T R	neg	gister of Deeds Stamp & File Number
4.	Lot No.	, Recorded Plat		
5.	Private Claims			A B C D E F G H I J K L I
in la cur Mai abo Cou exp	hereby certify that underines 1 and 2 above we werent manual of survey in agement or by a decre over were in conformancurt of Law; established pressed below:  TE: Not more than	r requirements of P.A. 74, Michigan P.A. of 1970, the in conformance with regulations and rules the instructions of the United States Department of the of a Court of Lawland/or that the corner points in elevation with the rules of the Michigan Board of Land State, re-established, monumented, re-monumented, and range.	herefore as required in the the Interior, Bureau of Land mentioned in lines 3, 4 and 5 urveyors or by a Decree of a sted, recovered, found as	2 6 5 4 3 2 1 4 4 7 8 9 10 11 12 12 15 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11
	on this certific	ite.		12 31 32 33 34 35 36
. <b>A</b> .	H-13, South corner 1840 GLO S 1883 Keep F- 1888 Keep F- 1894 Keep F- 1952 M. Feindt S 1953 M. Feindt S	nal monument and accessories and/or sub of Section 34, T35N, R5W, east of jog in Be et post N80°W, 14 links, 12" birch; N28°E, bund corner, ran N/L of sec. 3. (shows 130.0 bund corner, ran W 1/2 of S/L sec. 34. bund corner, subdivided sec. 34. burvey for Dean, found wood stake and repla burvey for Dean. (shows found iron 130.0' W burvey for Peterson (240/875) found 1-1/4" in	oyer Road , 29 links, 12" cedar 68' W. to Closing Cor. of sec. aced with iron pipe. // of fd IP at N 1/4 CC sec. 3.)	JOSEPH B. O'NEILL

H-13, South corner of Section 34, T35N, R5W, east of jog in Boyer Road Found as described and recorded in 1981 survey by J. Green. Witnesses fit well, and the history of the corner appears to be consistent with this position.

This corner is accepted by the Emmet County Remonumentation Peer Group as a careful and faithful perpetuation of the position of the original corner.

 Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-13, South corner of Section 34, T35N, R5W, east of jog in Boyer Road

1973 G. Young Survey #1029 shows found 1-1/4" iron pipe. (124.24' E of T-iron at CC sec. 3.)

1980 - present Numerous surveys showing found 1" (or called 1 1/4") iron pipe.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Survey for Rea (316/339), found 1" iron pipe. (124.2' W to Closing Cor.)

Found and replaced 1 1/4" iron pipe (4'long) found with a 2" dia. 30" long PVC pipe with a base magnet and a standard brass Emmet County Remonumentation cap, set 32.5' west of fence corner.

N37°E 55.43', found tag # 10710, S.W. face corner fence post

N90°E 32.49', found tag # 10710, W. face corner fence post N29°E 43.61', found tag # 33983, W. face 4" Red Pine

S68°W 107.90', found tag # 33983, S.W. face of Power Pole

N24°W 100.76', found tag # 33983, N.E. face of Power Pole

Preserved and buried found iron pipe south of corner, 1' deep, lying horizontally.

APPROVED LAND CORNER P.A. 345 OF 1990 Emmet County CELKE

30095

0 \$ 6 8 8 1

≡urveyor's Michigan License No. \_

Date March 18